



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2502312

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN: JASON TEA

INV Date 15/04/2025
Reference CD/FCI24100346/Aua3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMP 4618D
Insured Veh. SHA 2848H
Claim No. D24009196MFCT/CTPL/TPD 2
Policy No. D-24101861MFCT
Accident Date 16/10/2024
Inspection Date 21/10/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN:JASON TEA			Ref: CD/FCI24100346/Aua3q2(N) Date: 15/04/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 2848H	Veh. Inspected	SMP 4618D
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24009196MFCT/CTPL/TPD 2	Excess (\$)	0.00
	Assign From	JASON TEA	Assign Date	21/10/2024
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	RU11310908	Colour	BLACK
	Odometer	117246 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	MICHELIN	6 mm
	L/H Front Tyre	215/60 R16	MICHELIN	6 mm
	R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
	L/H Rear Tyre	215/60 R16	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/10/2024	Inspection Date	21/10/2024
	Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 4618D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR -RH	DENTED	989.40	989.40
1	FRONT DOOR LOCK RH	NOT NECESSARY	285.40	-
1	FRONT DOOR WEATHERSTRIP RH	NOT NECESSARY	145.20	-
1	FRONT DOOR INNER TRIM BOARD RH	NOT NECESSARY	645.10	-
1	FRONT DOOR GLASS REGULATOR C/W MOTOR RH	NOT NECESSARY	394.60	-
1	ROCKER PANEL OUTER SKIRT	TO REPAIR SEE LABOUR	678.20	-
1	REAR DOOR RH	DENTED	980.60	980.60
1	REAR DOOR LOCK RH	NOT NECESSARY	274.50	-
1	REAR DOOR WEATHERSTRIP RH	NOT NECESSARY	148.10	-
1	REAR DOOR VERTICAL WEATHERSTRIPE RH	CUT	99.40	99.40
1	REAR DOOR INNER TRIM BOARD RH	NOT NECESSARY	635.90	-
1	REAR DOOR GLASS REGULATOR C/W MOTOR RH	NOT NECESSARY	385.50	-
1	REAR FENDER ARC GARNISH RH	CUT	196.40	196.40
1	REAR AXLE	NOT NECESSARY	1,513.20	-
1	REAR WHEEL HUB C/W BEARING RH	NOT NECESSARY	335.40	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	330.70	-
	LESS 20% DISCOUNT		-1,607.52	-453.16
			6,430.08	1,812.64
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET FRONT DOOR BLACK TAPE (SN)	NECESSARY	60.00	60.00
1	SET ROCKER PANEL OUTER SKIRT CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR DOOR BLACK TAPE (SN)	NECESSARY	60.00	60.00
1	SET REAR FENDER ARC GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR WHEEL RIM (SN)	CUT	880.00	480.00
1	REAR TYRE (SN)	NOT NECESSARY	280.00	-
			1,390.00	620.00

Report Ref No. CD/FCI24100346/Aua3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO KNOCKING & PULL OUT RH FRONT PORTION & RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF ROCKER PANEL OUTER SKIRT.		800.00	500.00
	TO PUTTY AND SPRAY UP PAINT WORKS.		800.00	600.00
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO APPLY TUFF COAT.		150.00	30.00
	TO TRANSFER FRONT & REAR DOOR FITTINGS.		300.00	160.00
	TO REMOVE REAR UNDERCARRIAGE.	NOT NECESSARY	380.00	-
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
			2,630.00	1,400.00
	GRAND TOTAL		10,450.08	3,832.64
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,050.00

Report Ref No. CD/FCI24100346/Aua3q2(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SMP 4618D



PHOTOGRAPHS FOR VEHICLE NO. : SMP 4618D



PHOTOGRAPHS FOR VEHICLE NO. : SMP 4618D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : SMP 4618D



PHOTOGRAPHS FOR VEHICLE NO. : SMP 4618D



PHOTOGRAPHS FOR VEHICLE NO. : SMP 4618D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 7 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : SMP 4618D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 8 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : SMP 4618D

