



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2502106

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 08/04/2025
Reference CD/LPC24100348/Rma3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKJ 5299P
Insured Veh. GBK 4324H
Claim No. 24/24/24/VC05/030045
Policy No. Z24VC05025414
Accident Date 17/10/2024
Inspection Date 04/11/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CD/LPC24100348/Rma3q2 (N) Date: 08/04/2025 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBK 4324H	Veh. Inspected	SKJ 5299P
	Policy No.	Z24VC05025414	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030045	Excess (\$)	0.00
	Assign From	ERIC WOO	Assign Date	04/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	LAND ROVER DISCOVERY SPORT 2.0P	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	SALCA2AX1KH802314	Colour	BLACK
	Odometer	056789 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R19	PIRELLI	7 mm
	L/H Front Tyre	235/55 R19	PIRELLI	7 mm
	R/H Rear Tyre	235/55 R19	PIRELLI	7 mm
	L/H Rear Tyre	235/55 R19	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/10/2024	Inspection Date	04/11/2024
	Survey held at	WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKJ 5299P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	BENT	2,832.00	2,832.00
1	BOOT LID WEATHERSTRIP	TORN	198.00	198.00
1	BOOT LID LOCK	SERVICEABLE	204.00	-
1	BOOT LID LOGO BADGE	NECESSARY	82.00	82.00
1	BOOT LID EMBLEM DISCOVER	NECESSARY	238.00	238.00
1	BOOT LID EMBLEM SPORT	NECESSARY	144.00	144.00
1	REAR BUMPER	DEFORMED	2,472.00	2,472.00
2	REAR BUMPER SIDE RETAINER RH/LH @\$82.00	SERVICEABLE	164.00	-
1	REAR BUMPER REFLECTOR LH	CRACKED	296.00	296.00
1	REAR BUMPER LOWER GARNISH	DEFORMED	584.00	584.00
2	REAR BUMPER REVERSE SENSOR @\$202.00	SERVICEABLE	404.00	-
1	REAR REINFORCEMENT	BENT	1,158.00	1,158.00
1	EXHAUST PIPE LH	BENT	3,912.00	3,912.00
1	END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	END PANEL TOP GARNISH (ADDITIONAL)	CRACKED	396.00	396.00
	LESS 10% DISCOUNT		-1,308.40	-1,231.20
			11,775.60	11,080.80
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
1	REAR CARPLATE WITH HOLDER (SN)	SERVICEABLE	35.00	-
1	REAR BUMPER LOWER GARNISH CLIP(SN)	NECESSARY	30.00	30.00
			100.00	65.00
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND RELACE THE DAMAGED PARTS AND COMPONENTS .INCLUSIVE OF THE REPAIR OF END PANEL.		800.00	400.00
	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED .		600.00	200.00

Report Ref No. CD/LPC24100348/Rma3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL.		60.00	30.00
	TO REMOVE AND REPLACE REAR REVERSE SENSOR .		100.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN.		100.00	100.00
	TO REMOVE AND REPLACE EXHAUST PIPE .		200.00	80.00
	TO REMOVE AND REPLACE EXHAUST PIPE . (ADDITIONAL)	NOT NECESSARY	300.00	-
			2,160.00	870.00
GRAND TOTAL			14,035.60	12,015.80
RECOMMENDED COST OF REPAIRS				12,015.80

Report Ref No. CD/LPC24100348/Rma3q2(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor


HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 6 of 12)


PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P




PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P




PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P




PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P




PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P



PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 4 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SKJ 5299P

