

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24100353/AVP3E2
Date: 11/12/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SKK4109G **Insured Vehicle No :** SLS8321D

Date of Loss: 26/12/2023 Nature of Claim: TP Claim No: DMPC2301174H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK4109G**

Make & Model: BMW 318I, 2.0 (A) Engine No: F1673928B48B20A

Reg. Date: 30/11/2021 (Man. Year: 2021) Chassis No: WBA70DY0608B99079

Colour: Green Odometer: 63798 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,776.95	6,491.40	8,285.55	56.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,410.00	860.00	3,550.00	80.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,186.95	7,351.40	11,835.55	61.69
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	19,186.95	5,800.00	13,386.95	69.77
+ GST 9.00/9.00% (S\$)	1,726.83	522.00	1,204.83	69.77
Nett Amount (S\$)	20,913.78	6,322.00	14,591.78	69.77

INSPECTION

Date of Assignment: 21/10/2024

Date Inspected: 22/10/2024 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2024)
Parts:	143	BMW 318I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK4109G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Not Necessary	1,709.00 FL	*- FL
2	1	*BONNET EMBLEM	Not Necessary	78.00 FL	*- FL
3	1	*SET BONNET EMBLEM LOCK CLIPS	Not Necessary	28.00 FL	*- FL
4	1	*FRONT BUMPER	Deformed	1,367.00 FL	*1,367.00 FL
5	1	*FRONT BUMPER LH SIDE RETAINER	Not Necessary	73.00 FL	*- FL
6	1	*FRONT BUMPER RH SIDE RETAINER	Not Necessary	73.00 FL	*- FL
7	1	*FRONT BUMPER LOWER GRILLE	Not Necessary	276.00 FL	*- FL
8	1	*FRONT BUMPER LH SIDE COVER	Cut	83.00 FL	*83.00 FL
9	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	607.00 FL	*- FL
10	1	*FRONT BUMPER IMPACT ABSORBER	Not Necessary	92.00 FL	*- FL
11	1	*FRONT BUMPER LOWER REINFORCEMENT	Not Necessary	329.00 FL	*- FL
12	1	*FRONT BUMPER LH SIDE PARKING SENSOR	Not Necessary	382.00 FL	*- FL
13	1	*FRONT BUMPER LH CENTRE PARKING SENSOR	Damaged	382.00 FL	*290.00 FL
14	4	*FRONT BUMPER PARKING SENSOR HOLDERS	Necessary	44.00 FL	*44.00 FL
15	1	*FRONT BUMPER PARKING SENSOR RUBBER SEAL (4PCS)	Necessary (1Pc Only)	96.00 FL	*20.00 FL
16	1	*LH HEADLAMP ASSY	Cracked	3,748.00 FL	*3,410.00 FL
17	1	*LH HEADLAMP BRACKET	Not Necessary	96.00 FL	*- FL
18	1	*FRONT LH SPORT RIM	Cut	1,198.00 FL	*1,198.00 FL
19	1	*FRONT LH WHEEL BEARING	Not Necessary	563.00 FL	*- FL
20	1	*FRONT LH SHOCK ABSORBER	Not Necessary	622.00 FL	*- FL
21	1	*FRONT LH LOWER ARM	Not Necessary	506.00 FL	*- FL
22	1	*FRONT SHOCK ABSORBER	Not Necessary	629.00 FL	*- FL
23	1	*BONNET BODY WRAP STICKER	Not Necessary	900.00 FS	*- FS
24	1	*FRONT BUMPER BODY WRAP STICKER	Necessary	850.00 FS	*400.00 FS
25	2	*FRONT BUMPER PARKING SENSOR BODY WRAP STICKERS	Not Necessary	30.00 FS	*- FS
26	1	*FRONT LH TYRE	Not Necessary	580.00 FS	*- FS
27	1	*BRAKE FLUID	Not Necessary	85.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,426.00	6,812.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	649.05	320.60
Total Parts (\$\$)	14,776.95	6,491.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,300.00	300.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	250.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	60.00	0.00
5	REMOVE AND REPLACE FRONT BUMPER PARKING SENSORS AND HOLDERS	New	150.00	50.00
6	RECODING AND PROGRAM HEADLAMPS ASSY	New	950.00	150.00
7	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	120.00	80.00
8	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	550.00	0.00
Gross Labour Cost (S\$)			4,410.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >