

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

NW BATTERIEN TRADING ENTERPRISE PTE
LTD
53 UBI AVENUE 1 #03-39 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

TP INC.
Veron

Contact : 98216625 92373162

TAX INVOICE

Repair Code : CLM18425

Date in : 17/10/2024

Vehicle Num. : GBD150E

Model : TOYOTA DYNA 3.0 DIESEL TURBO M/T 2WD LORRY

Chassis/Eng# : KDY2318014811/1KD2371821

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Rehd</i>	1	895.20	<i>✓</i> 895.20
FRONT BUMPER FOGLAMP GARNISH RH <i>new</i>	1	105.00	<i>+</i> 105.00
FRONT BUMPER FOGLAMP RH <i>new</i>	1	235.70	<i>+</i> 235.70
FRONT BUMPER INNER BRAK CET RH <i>new</i>	1	150.50	<i>+</i> 150.50
FRONT BUMPER INNER REINFORCEMENT <i>new</i>	1	182.20	<i>+</i> 182.20
FRONT GRILLE <i>Build</i>	1	595.20	<i>2</i> 595.20
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	90.20	<i>✓</i> 90.20
FRONT HEADLAMP RH <i>ok</i>	1	892.90	<i>✓</i> 892.90
Subtotal before discount			3,146.90
Percentage discount 25%			786.73
Sub-total 1			2,360.18
FRONT GRILLE CLIPS - SET <i>new</i>	1 <i>30</i>	50.00	<i>30</i> 50.00
FRONT HEADLAMP CLIPS RH - SET <i>new</i>	1	25.00	<i>+</i> 25.00
Subtotal before discount			75.00
Percentage discount 0%			0.00
Sub-total 2			75.00
Parts-total			2,435.18

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

NW BATTERIEN TRADING ENTERPRISE PTE
LTD
53 UBI AVENUE 1 #03-39 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Contact : 98216625 92373162

TAX INVOICE

Repair Code : CLM18425

Date in : 17/10/2024

Vehicle Num. : GBD150E

Model : TOYOTA DYNA 3.0 DIESEL TURBO M/T 2WD LORRY

Chassis/Eng# : KDY2318014811/1KD2371821

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

30 80.00

730 400 500.00

300 500.00

X 60.00

1,140.00

3,575.18

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin Lj
r/s 22/10/24
03 Days

total: 2615.12

c/s: 2/c ✓