

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24100362/UQP3E2

Date: 28/10/2024

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001372431		
Claimant Vehicle No :	SMP5456Y	Insured Vehicle No :	SJP9069R		
Date of Loss:	20/10/2024	Nature of Claim:	TP	Claim No:	377366

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP5456Y	Engine No:	CZD737786
Make & Model:	SKODA KODIAQ, 1.4 TSI AMBITION PLUS (A)	Chassis No:	TMBKC7NS5K8502610
Reg. Date:	30/09/2019 (Man. Year: 2019)	Odometer:	63061 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts	Parts : 5,486.39	27,287.00	7,155.90	20,131.10	73.78
Miscellaneous Items	10% 4,337.75	0.00	0.00	0.00	
Labour	Lab 1,490.00	3,700.00	1,490.00	2,210.00	59.73
Paintwork Labour	Total 6,277.75	0.00	0.00	0.00	
Towing	I/s 5,100.00	0.00	0.00	0.00	
Calculated Gross Total (S\$)		30,987.00	8,645.90	22,341.10	72.10
Approved Total (Overridden) (S\$)			6,900.00		
(S\$)		30,987.00	6,900.00	24,087.00	77.73
+ GST 9.00/9.00% (S\$)		2,788.83	621.00	2,167.83	77.73
Nett Amount (S\$)		33,775.83	7,521.00	26,254.83	77.73

INSPECTION

Date of Assignment: 22/10/2024

Date Inspected: 22/10/2024 Inspected At:

Estimated Period of Repair: 5.0 days

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

ASRKJ 18/11/2024

(FOR MANDATE ONLY)

Parts 6,158.79
10% 5,542.91
Lab 1,490.00
Total 7,032.91
L/Sum 5,600.00

ASRKJ ON 03/12/2024

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Oct 2024)
Parts:	144	SKODA KODIAQ 1.4 TSI AMBITION PLUS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP5456Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	4,215.00 F	*- FL
2	1		*TAILGATE REAR LOGO	Not Necessary	158.00 F	*- FL
3	1		*TAILGATE SKODA EMBLEM	Serviceable	125.00 F	*- FL
4	1		*TAILGATE KODIAQ EMBLEM	Serviceable	115.00 F	*- FL
5	1		*TAILGATE WEATHERSTRIP	Serviceable	495.00 F	*- FL
6	1		*TAILGATE INNER LOCK	Not Necessary	655.00 F	*- FL
7	1		*REAR BUMPER TOP	Deformed / Torn	2208.20 3,800.00 F	*3,100.00 FL
8	1		*REAR BUMPER LOWER	Distorted	473.78 3,200.00 F	*1,122.00 FL
9	1		*REAR BUMPER TOP BLACK CENTRE GARNISH	Cut / Torn	267.66 580.00 F	*285.00 FL
10	2		*REAR BUMPER LAMPS	Not Necessary	430.00 F	*- FL
11	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	296.00 F	*- FL
12	1		*REAR BUMPER SPONGE	Torn	366.00 F	*231.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Not Fitted	1,415.00 F	*- FL
14	1		*REAR BUMPER INNER TOP RETAINER	Cracked	445.00 F	*250.00 FL
15	1		*REAR BUMPER PDC SENSORS	Malfunction (2Pcs Only)	1,000.00 F	*430.00 FL
			(4PCS)			
16	1		*REAR BUMPER PDC SENSOR WIRE	Not Necessary	366.00 F	*- FL
17	1		*REAR BUMPER UNDER LOWER COVER	Deformed / Cracked	520.00 F	*292.00 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
19	1		*REAR END PANEL	Dented / Bent	1,400.00 F	*856.00 FL
20	1		*REAR END PANEL TOP GARNISH	Not Necessary	565813309 421.00 F	*- FL
21	1		*REAR FENDER OUTER PROTECTOR N/S	Deformed / Torn	210.15 455.00 F	*445.00 FL
22	1		*REAR EXHAUST ASSY	Repair	3,215.00 F	*- FL
23	1		*REAR EXHAUST MOUNTING	Not Necessary	60.00 F	*- FL
24	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	425.00 F	*- FL
25	1		*TAILLAMP N/S	Cracked	980.00 F	*890.00 FL
26	1		*REAR BLIND SPOT SENSOR UNIT	Serviceable	2,100.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	27,287.00	7,951.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	795.10
Total Parts (\$\$)	27,287.00	7,155.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	100.00	30.00
3	TO TRANSFER TAILGATE MECHANISM	New	120.00	0.00
4	TO DISMANTLE & REFIX REAR TAILGATE GLASS	New	150.00	0.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	60.00
6	TO DISMANTLE & REPLACED REAR EXHAUST	New	180.00	0.00
7	TO SPRAY PROOFING	New	100.00	30.00
8	TO RESET & REPROGRAMME SYSTEM	New	180.00	50.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	600.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	700.00
Gross Labour Cost (\$\$)			3,700.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >