12/18/24, 2:49 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24100365/KVP3E2

Date: 18/12/2024

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001451188

Claimant Vehicle No: SNQ6598Y Insured Vehicle No: SMT8924Y

Date of Loss: 20/10/2024 Nature of Claim: TP Claim No: 377372

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNQ6598Y

Make & Model: BYD SEAL, PERFORMANCE (A) Engine No: HIDDEN

Reg. Date: 30/08/2023 (Man. Year: 2023) Chassis No: LGXCF6CD0P2166145

Colour: Metallic Blue Odometer: 13149 km

Engine Capacity: 0 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45Z R19 Rear Tyre Size: 235/45Z R19
Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm
Front Right Side: Michelin 9 mm
Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,875.50	1,888.50	2,987.00	61.27
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,170.00	875.00	295.00	25.21
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Gross To	otal (S\$)	6,045.50	2,763.50	3,282.00	54.29
+ GST 9.00/9.0	0% (S\$)	544.10	248.72	295.38	54.29
Nett Amo	unt (S\$)	6,589.60	3,012.22	3,577.38	54.29

INSPECTION

Date of Assignment: 22/10/2024

Optima Werkz Pte Ltd (HQ)

Date Inspected: 23/10/2024 Inspected At: 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK

Autopoint

Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

12/18/24, 2:49 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Dec 2024)

Parts: 143 BYD SEAL PERFORMANCE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNQ6598Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

	*RR BUMPER (NPA)			
	ICIC DOMI LIC (ICI A)	Repair	0.00 FL	*- FL
	*LHR FENDER FIX GLASS	Cut	1,040.00 FL	*1,040.00 FL
	*LHR FENDER (NPA)	Repair	0.00 FL	*- FL
	*LHR DOOR (NPA)	Repair	0.00 FL	*- FL
	*LHR DOOR WINDOW GLASS	Cut	640.00 FL	*640.00 FL
	*LHR DOOR EXT. TRIM PANEL	Cut	320.00 FL	*320.00 FL
	*LHR WHEEL COVER	Cut	65.00 FL	*65.00 FL
	*LHR RIM	Serviceable	2,430.00 FL	*- FL
	*LHR FIX GLASS SEALANT	Necessary	30.00 FS	*30.00 FS
	*LHF LIVERY	Not Necessary	800.00 FS	*-FS
nise part. S=SpcNe	tt. L=ListItemDisc.	<u> </u>		
		Sub Total (S\$)	5,325.00	2,095.00
	- List Item Discour	nt on L Items 10.00/10.00% (S\$)	449.50	206.50
		Total Parts (S\$)	4,875.50	1,888.50
ni	se part. S=SpcNe	*LHR DOOR (NPA) *LHR DOOR WINDOW GLASS *LHR DOOR EXT. TRIM PANEL *LHR WHEEL COVER *LHR RIM *LHR FIX GLASS SEALANT *LHF LIVERY se part. S=SpcNett. L=ListItemDisc.	*LHR DOOR (NPA) *LHR DOOR WINDOW GLASS Cut *LHR DOOR EXT. TRIM PANEL Cut *LHR WHEEL COVER Cut *LHR RIM Serviceable *LHR FIX GLASS SEALANT Necessary *LHF LIVERY Not Necessary se part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)	*LHR DOOR (NPA) *LHR DOOR WINDOW GLASS Cut *LHR DOOR EXT. TRIM PANEL Cut *LHR WHEEL COVER Cut *LHR RIM Serviceable *LHR FIX GLASS SEALANT Necessary *LHF LIVERY Not Necessary *See part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$) 449.50

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, REPLACE, REPAIR, READJUST & REFIX SIDE AFFECTED AREAS	New	400.00	200.00
2	TO PERFORM WIRING CHECKS ON ELECTRICAL SYSTEMS	New	30.00	15.00
3	TO REMOVE, PUTTY, REPAIR, SAND AND RESPRAY AFFECTED AREAS	New	600.00	600.00
4	TO REMOVE, REPLACE & REFIX BUMPER SENSORS	New	30.00	0.00
5	TO REMOVE, REPLACE & REINSTALL DOOR INNER MECHANISM	New	30.00	0.00
6	TO REMOVE, REFIX & REPLACE SIDE QUARTER GLASS	New	80.00	60.00
	Gross Labo	ur Cost (S\$)	1,170.00	875.00
	Report was unsubmitted during this p	print-out.		

< END OF ESTIMATES >