

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24100366/Anh3m4(N)	
	75 BRAS BASAH R INCOME CENTRES	ROAD SINGAPORE 189557		Date:	22/10/2024	
	ATTN: ASTER QUE	≣K		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJY 1533Y	Veh. Inspected	k	SDK 11M	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1284468-001	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		22/10/2024	
2. Vehicle Particulars & Condition						
	Make & Model	JAGUAR XE	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	SAJAB4AX4JCP36426	Colour		RED	
	Odometer	100796 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/40R18	GOODYEAR		6 mm	
	L/H Front Tyre	245/40R18	GOODYEAR		6 mm	
	R/H Rear Tyre	245/40R18	GOODYEAR		6 mm	
	L/H Rear Tyre	245/40R18	GOODYEAR		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	29/06/2024	Inspect Date /	Time	22/10/2024 ( 02:55 PM )	
	Survey held at	RYDER AUTO PTE LTD				
		2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	ia. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					