



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100374/Uqp3m4
16 RAFFLES QUAY	Date:	01/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7607L	Veh. Inspected	SNK 7405X
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24009273MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	22/10/2024

2. Vehicle Details

Make & Model	HONDA SHUTTLE HYBRID 1.5G AUTO	C.C	1496
Engine No.	LEB7608067	Year of Reg.	09/05/2023
Chassis No.	GP72206613	Colour	WHITE
Odometer	73362 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60R15	DUNLOP	6
L/H Front Tyre	185/60R15	DUNLOP	6
R/H Rear Tyre	185/60R15	DUNLOP	6
L/H Rear Tyre	185/60R15	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/10/2024	Inspection Date	22/10/2024
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days