



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: AMANDA CHOOI

Ref: CS/INC24060227/Anh3m4(N)

Date: 18/02/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SML 4593L	Veh. Inspected	SLX 5253K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1282884-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	25/06/2024

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CLA200	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WDD1173432N620907	Colour	WHITE
Odometer	93955 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/35R19	MICHELIN	6 mm
L/H Front Tyre	235/35R19	MICHELIN	6 mm
R/H Rear Tyre	235/35R19	MICHELIN	6 mm
L/H Rear Tyre	235/35R19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/06/2024	Inspect Date / Time	25/06/2024 (11:52 AM)
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days