



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNR 8446J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BONNET GARNISH	TO REPAIR SEE LABOUR	\$275.60	\$0.00
1	FRONT O/S FENDER	TO REPAIR SEE LABOUR	\$955.60	\$0.00
1	FRONT O/S HEADLAMP	CRACKED	\$3,050.70	\$3,050.70
1	FRONT O/S HEADLAMP GARNISH	DENTED	\$205.10	\$205.10
1	FRONT O/S HEADLAMP TOP PANEL	TO REPAIR SEE LABOUR	\$197.50	\$0.00
1	FRONT RADIATOR SUPPORT PANEL	TO REPAIR SEE LABOUR	\$1,780.20	\$0.00
1	FRONT GRILLE BASE - UPPER	CRACKED	\$286.70	\$286.70
1	FRONT GRILLE BASE - LOWER	CRACKED	\$385.30	\$385.30
1	FRONT GRILLE TOP OUTER COVER	DENTED	\$285.60	\$285.60
2	FRONT GRILLE TOP OUTER COVER MOULDING @\$197.30	NECESSARY	\$394.60	\$394.60
1	FRONT GRILLE CENTRE OUTER COVER	CRACKED	\$376.80	\$376.80
1	FRONT GRILLE CENTRE OUTER COVER MOULDING	NECESSARY	\$205.10	\$205.10
1	FRONT GRILLE EMBLEM	NECESSARY	\$75.10	\$75.10
1	FRONT GRILLE LOWER OUTER COVER	CRACKED	\$236.70	\$236.70
1	FRONT GRILLE LOWER OUTER COVER MOULDING	NECESSARY	\$230.20	\$230.20
1	FRONT BUMPER	BUCKLED/CRACKED	\$1,276.20	\$1,050.40
1	FRONT O/S BUMPER SIDE RETAINER	DISTORTED	\$95.10	\$95.10
1	FRONT BUMPER REINFORCEMENT	BENT	\$550.10	\$510.00
1	FRONT BUMPER SPONGE	CRACKED	\$185.60	\$185.60
1	FRONT O/S BUMPER FOG LAMP GARNISH	SERVICEABLE	\$135.70	\$0.00
	LESS 25.00% DISCOUNT		(\$2,795.88)	(\$1,893.25)
			\$8,387.62	\$5,679.75

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF FRONT BONNET GARNISH, FRONT O/S FENDER, FRONT O/S HEADLAMP TOP PANEL AND FRONT RADIATOR SUPPORT PANEL		\$1,200.00	\$400.00
	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION		\$1,200.00	\$450.00
	CHECK / RECONNECT WIRING		\$60.00	\$20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour			
	Description of Parts	Condition	Workshop Estimate (\$) Our Adjusted (\$)
	REMOVE / REFIT AIR CON CONDENSER & TOP UP GAS	NOT NECESSARY	\$180.00 \$0.00
			\$2,640.00 \$870.00
GRAND TOTAL			\$11,027.62 \$6,549.75
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$5,200.00
Report Ref No: CS/AGI24100376/Kqp3e2			

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.