

ASS. REC. BY:

REF:

C91/AGI24/00376/K9P3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 GIA & EN not ready

11/11 11:20 85200 Cntr Cnd \$5827.63, 53%

Date/Time, File Pass to?

1) W/H M/ist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) TP 5200

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Veh No:

SNR 848J Yr Regn: 09, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Noah C.C. 1797

Colour

M. Black A/C: Insured / Std / NI / NA

Sp. Reading

110049 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZWR 80 0402802

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/35R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9 mm

R/Bal.

9 mm

L/Bal.

9 mm

L/Bal.

9 mm

D.O.A.

21/10/24

D.O.I.

22/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

1st O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Ong See Choon
Blk 864A Tampines St 83
#08-446 Singapore 521864

Vehicle No : SNR 8446 J
Make : Toyota Noah
Year : 2019

NOT Withair
L1 Sy \$5200p
Repair After Paint
3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front bonnet garnish	
1 pc	Front o/s fender	
1 pc	Front o/s headlamp	
1 pc	Front o/s headlamp garnish	
1 pc	Front o/s headlamp top panel	
1 pc	Front radiator support panel	
1 pc	Front grille base - upper	
1 pc	Front grille base - lower	
1 pc	Front grille top outer cover	
2 pcs	Front grille top outer cover moulding	
1 pc	Front grille centre outer cover	
1 pc	Front grille centre outer cover moulding	
1 pc	Front grille emblem	
1 pc	Front grille lower outer cover	
1 pc	Front grille lower outer cover moulding	
1 pc	Front bumper	
1 pc	Front o/s bumper side retainer	
1 pc	Front bumper reinforcement	
1 pc	Front bumper sponge	
1 pc	Front o/s bumper fog lamp garnish	

photo
photo

1050.40

510 photo
photo

R	SCA	\$275.60	X
R		\$955.60	X
CM		\$3,050.70	X
RL		\$205.10	X
R		\$197.50	X
R		\$1,780.20	X
CM		\$286.70	X
CM		\$385.30	X
RL		\$285.60	X
\$197.30	R	\$394.60	X
CM		\$376.80	X
RL		\$205.10	X
RL		\$75.10	X
CM		\$236.70	X
RL		\$230.20	X
RL	1CM	\$1,276.20	X
DI		\$95.10	X
B		\$550.10	X
CM		\$185.60	X
R		\$135.70	X
		\$11,183.50	
Less 25 %		\$2,795.87	
		\$8,387.63	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,200.00 400

To putty & spray paint on accident affected portion.

\$1,200.00 450

Check/reconnect wiring.

\$60.00 20

Remove/refit air con condenser & top up gas

RL \$180.00 X

Total \$11,027.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: