

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100379/KMA3Q2**Date:** 01/08/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220105649
Claimant Vehicle No :	SNG9261B	Insured Vehicle No :	GU8200T
Date of Loss:	17/10/2024	Nature of Claim:	TP
		Claim No:	6022724253SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG9261B	Engine No:	K9KF649D060274
Make & Model:	RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A)	Chassis No:	VF1RFA00063211927
Reg. Date:	15/09/2022 (Man. Year: 2019)	Odometer:	205376 km
Colour:	Metallic Pearl White		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R20	Rear Tyre Size:	195/55 R20
Front Left Side:	Bridgestone 2 mm	Rear Left Side:	Grenlander 8 mm
Front Right Side:	Bridgestone 2 mm	Rear Right Side:	Grenlander 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	70,642.00	54,832.00	15,810.00	22.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,190.00	4,830.00	4,360.00	47.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	79,832.00	59,662.00	20,170.00	25.27
Approved Total (Overridden) (S\$)		45,000.00		
(S\$)	79,832.00	45,000.00	34,832.00	43.63
+ GST 9.00/9.00% (S\$)	7,184.88	4,050.00	3,134.88	43.63
Nett Amount (S\$)	87,016.88	49,050.00	37,966.88	43.63
+ Car Rental (42.0 x S\$100.00/day + 9.00% GST) (S\$)		4,578.00		
+ Doc/Search Fee (S\$)		33.18		
+ Other Costs (S\$)		22.67		
Nett Liability (S\$)		53,683.85		
Global Sum Settlement (S\$)		53,500.00		

INSPECTION

Date of Assignment:	23/10/2024	Optima Werkz Pte Ltd (HQ)
Date Inspected:	23/10/2024 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	18.0 days	Singapore 568047

Adjuster: KENNETH KONG

Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,500.00 FL	*1,500.00 FL
2	1		*REAR LH BUMPER RETAINER	Cracked	500.00 FL	*500.00 FL
3	1		*REAR RH BUMPER RETAINER	Serviceable	500.00 FL	*- FL
4	1		*REAR LH BUMPER SIDE SUPPORT BRACKET	Bent	300.00 FL	*300.00 FL
5	1		*REAR RH BUMPER SIDE SUPPORT BRACKET	Cracked	300.00 FL	*300.00 FL
6	1		*REAR BUMPER LOWER	Bent	1,200.00 FL	*1,200.00 FL
7	1		*REAR BUMPER LOWER OUTER MOULDING	Bent	1,000.00 FL	*1,000.00 FL
8	1		*REAR LH BUMPER REFLECTOR	Cracked	420.00 FL	*420.00 FL
9	4		*REAR REVERSE SENSOR	Shorted (2 PCS ONLY)	1,700.00 FL	*850.00 FL
10	1		*REAR BUMPER CENTER BRACKET	Cracked	450.00 FL	*450.00 FL
11	1		*REAR BUMPER TOWING COVER	Dented	120.00 FL	*120.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	900.00 FL	*900.00 FL
13	1		*REAR LH BUMPER UNDER COVER	Distorted	300.00 FL	*300.00 FL
14	1		*REAR BUMPER CENTER UNDER COVER	Cracked	450.00 FL	*450.00 FL
15	1		*REAR LH BUMPER LOWER BRACKET	Bent	300.00 FL	*300.00 FL
16	1		*REAR RH BUMPER LOWER BRACKET	Repair	280.00 FL	*- FL
17	2		*REAR BUMPER CENTER INNER LOWER BRACKET	Cracked	560.00 FL	*560.00 FL
18	1		*TAILLAMP LH	Broken	960.00 FL	*960.00 FL
19	1		*TAILLAMP RH	Serviceable	960.00 FL	*- FL
20	1		*REAR END PANEL OUTER	Bent	1,800.00 FL	*1,800.00 FL
21	1		*REAR LH END PANEL OUTER EXTENSION	Bent	750.00 FL	*750.00 FL
22	1		*REAR END PANEL INNER	Bent	1,500.00 FL	*1,500.00 FL
23	1		*REAR END PANEL TRIM BOARD	Mtg Cracked	680.00 FL	*680.00 FL
24	1		*SMART KEY ANTENNA	Cracked	90.00 FL	*90.00 FL
25	1		*REAR BOOT	Bent	4,000.00 FL	*4,000.00 FL
26	1		*REAR BOOT RENAULT LOGO	Necessary	300.00 FL	*300.00 FL
27	1		*REAR BOOT SCENIC EMBLEM	Necessary	200.00 FL	*200.00 FL
28	1		*REAR BOOT RENAULT EMBLEM	Necessary	280.00 FL	*280.00 FL
29	1		*BOOT REFLECTOR LAMP LH	Broken	950.00 FL	*950.00 FL
30	1		*BOOT REFLECTOR LAMP RH	Mtg Cracked	950.00 FL	*950.00 FL
31	1		*REAR BOOT OUTER GARNISH	Cracked	1,400.00 FL	*1,400.00 FL
32	1		*REAR BOOT WEATHERSTRIP	Distorted / Dented	500.00 FL	*500.00 FL
33	1		*REAR BOOT LOCK	Jammed	250.00 FL	*250.00 FL
34	1		*REAR BOOT OUTER STRIP MOULDING	Cracked	800.00 FL	*800.00 FL
35	1		*REAR SPOILER	Mtg Cracked	1,400.00 FL	*1,400.00 FL
36	1		*REAR WINDSCREEN	Shattered	1,800.00 FL	*1,800.00 FL
37	1		*REAR WIPER ARM	Serviceable	300.00 FL	*- FL
38	1		*REAR WIPER BLADE	Serviceable	150.00 FL	*- FL
39	1		*REAR BOOT OUTER OPENING SWITCH	Serviceable	200.00 FL	*- FL
40	1		*REAR LICENCE PLATE LAMP	Serviceable	90.00 FL	*- FL
41	1		*REAR BOOT INNER LOWER TRIM BOARD	Cracked	1,500.00 FL	*1,500.00 FL
42	1		*REAR BOOT INNER UPPER TRIM BOARD	Mtg Cracked	360.00 FL	*360.00 FL
43	1		*REAR LH BOOT INNER UPPER TRIM BOARD	Serviceable	400.00 FL	*- FL
44	1		*REAR RH BOOT INNER UPPER TRIM BOARD	Serviceable	340.00 FL	*- FL
45	1		*REAR LH BOOT HINGE	Repair	560.00 FL	*- FL
46	1		*REAR RH BOOT HINGE	Repair	560.00 FL	*- FL
47	1		*REAR LH BOOT STRUT	Serviceable	300.00 FL	*- FL
48	1		*REAR RH BOOT STRUT	Serviceable	300.00 FL	*- FL
49	1		*REAR LH LUGGAGE SIDE TRIM	Dented	1,300.00 FL	*1,300.00 FL
50	1		*REAR LH LUGGAGE SIDE TRIM CENTER GARNISH	Cracked	1,000.00 FL	*1,000.00 FL
51	1		*REAR LH LUGGAGE SIDE TRIM UPPER GARNISH	Cracked	2,200.00 FL	*2,200.00 FL
52	1		*REAR RH LUGGAGE SIDE TRIM	Serviceable	1,300.00 FL	*- FL
53	1		*REAR RH LUGGAGE SIDE TRIM UPPER GARNISH	Cracked	2,100.00 FL	*2,100.00 FL
54	1		*ROOF LINING	Deformed	3,600.00 FL	*3,600.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*REAR ROOF PANEL	Repair	6,100.00 FL	*- FL
56	1		*REAR ROOF PANEL INNER MEMBER COVER	Deformed	3,600.00 FL	*3,600.00 FL
57	1		*REAR LH FENDER PANEL OUTER	Buckled	4,850.00 FL	*4,850.00 FL
58	1		*REAR LH FENDER PANEL AIR VENT	Serviceable	150.00 FL	*- FL
59	1		*TAILLAMP PANEL LH	Broken	1,050.00 FL	*1,050.00 FL
60	1		*REAR LH FENDER PANEL QUARTER GLASS	Not Necessary	1,000.00 FL	*- FL
61	1		*REAR EXHAUST TAIL PIPE	Bent	1,200.00 FL	*1,200.00 FL
62	1		*REAR EXHAUST TAIL PIPE HEAT SHIELD -FRONT	Serviceable	360.00 FL	*- FL
63	1		*REAR EXHAUST TAIL PIPE HEAT SHIELD -REAR	Dented	400.00 FL	*400.00 FL
64	1		*REAR AXLE	Bent	7,800.00 FL	*7,800.00 FL
65	1		*REAR LH AXLE STUB	Not Necessary	1,600.00 FL	*- FL
66	1		*REAR LH ABS SENSOR BRACKET	Repair	120.00 FL	*- FL
67	1		*REAR LH BRAKE DISC DUCT COVER	Serviceable	100.00 FL	*- FL
68	1		*REAR LH SUSPENSION SHOCK ABSORBER	Bent	360.00 FL	*360.00 FL
69	1		*REAR LH ABS SENSOR	Serviceable	180.00 FL	*- FL
70	1		*REAR LH WHEEL RIM (NPA)	Repair	0.00 FL	*- FL
71	1		*REAR LH DOOR PANEL (NPA)	Repair	0.00 FL	*- FL
72	1		*REAR RH FENDER PANEL (NPA)	Repair	0.00 FL	*- FL
73	1		*REAR LH CHASSIS (NPA)	Repair	0.00 FL	*- FL
74	1		*REAR RH CHASSIS (NPA)	Repair	0.00 FL	*- FL
75	1		*REAR ROOF INNER MEMBER (NPA)	Repair	0.00 FL	*- FL
76	1		*REAR BUMPER CLIPS	Necessary	55.00 FS	*55.00 FS
77	1		*REAR BUMPER LOWER CLIPS	Necessary	50.00 FS	*50.00 FS
78	1		*REAR BUMPER UNDER COVER CLIPS	Necessary	50.00 FS	*50.00 FS
79	1		*REAR BOOT INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
80	1		*REAR WINDSCREEN AND QUARTER GLASS SEALANT	Necessary	150.00 FS	*40.00 FS
81	1		*REAR WINDSCREEN AND QUARTER GLASS PRIMER	Necessary	100.00 FS	*30.00 FS
82	1		*REAR WINDSCREEN MOULDING	Necessary	150.00 FS	*150.00 FS
83	1		*REAR RECORDING CAMERA ON REAR WINDSCREEN	Dented	500.00 FS	*500.00 FS
84	1		*REAR WINDSCREEN SOLAR FILM	Necessary	400.00 FS	*200.00 FS
85	1		*REAR BOOT OUTER GARNISH CLIP	Necessary	50.00 FS	*50.00 FS
86	1		*REAR END PANEL OUTER & INNER SEALANT	Necessary	150.00 FS	*30.00 FS
87	1		*REAR FENDER PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
88	1		*REAR LICENCE PLATE NUMBER WITH FRAME	Dented	55.00 FS	*45.00 FS
89	1		*TAILLAMP GUIDE CLIPS	Dented	50.00 FS	*40.00 FS
90	1		*SET REAR REVERSE SENSOR MOUNTING BRACKET	Necessary	200.00 FS	*150.00 FS
91	1		*SET REAR EXHAUST TAIL PIPE MOUNTING AND GASKET	Necessary	50.00 FS	*50.00 FS
92	1		*REAR SPOILER CLIPS	Necessary	50.00 FS	*50.00 FS
93	1		*ROOF LINING CLIPS	Necessary	50.00 FS	*50.00 FS
94	1		*REAR ROOF PANEL SEALANT	Not Necessary	100.00 FS	*- FS
95	1		*REAR WINDSCREEN PRIVATE HIRE DECAL FROM LTA	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	78,220.00	60,740.00
- List Item Discount on L Items 10.00/10.00% (\$)	7,578.00	5,908.00
Total Parts (\$)	70,642.00	54,832.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	2,800.00	2,000.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT ,REAR BUMPER ,REAR END PANEL OUTER & INNER ,REAR LH & RH FENDER, REAR LH DOOR ,REAR BOOT OUTER GARNISH ,REAR LH CHASSIS ,TAILLAMP PANEL LH, REAR END PANEL OUTER EXTENSION ,REAR ROOF INNER MEMBER ,REAR BODY DRIP PANEL	New	3,500.00	1,400.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN AND QUARTER GLASS TO ENABLE BODYWORK REPAIR	New	180.00	180.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	60.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	200.00	120.00
7	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	250.00	200.00
8	TO CHECK WIRING & ELECTRICAL SYSTEM	New	120.00	20.00
9	TO REMOVE AND REFIT REAR LUGGAGE COMPARTMENT INNER TRIMMINGS ,LININGS,COVER ,CUSHION SEAT ,GARNISH AND OTHER NEC ITEMS TO ENABLE BODYWORK REPAIR	New	650.00	120.00
10	TO R&R TYRE AND RIM	New	100.00	0.00
11	TO REMOVE AND REFIT REAR UNDERCARRIAGE PARTS TO ENABLE BODYWORK REPAIR	New	400.00	300.00
12	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	New	150.00	60.00
13	TO REMOVE AND REFIT REAR EXHAUST PIPE TO ENABLE BODYWORK REPAIR	New	170.00	60.00
14	MOUNT WORKBENCH TO REALIGNMENT REAR CHASSIS AND REPAIR ACCIDENT AREAS	New	450.00	250.00
Gross Labour Cost (\$\$)			9,190.00	4,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >