

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EGI24100380/UNP3E2  
**Date:** 21/11/2024REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	CDMCG24002735
<b>Claimant Vehicle No :</b>	YP82H	<b>Insured Vehicle No :</b>	YQ3801A
Date of Loss:	18/10/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>YP82H</b>		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEN (CBU) (M)	Engine No:	4P10B88154
Reg. Date:	20/11/2015 (Man. Year: 2015)	Chassis No:	FEB21EA10562
Colour:	White	Odometer:	204872 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15 (D)
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,170.00	7,450.00	4,720.00	38.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,880.00	2,000.00	2,880.00	59.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>17,050.00</b>	<b>9,450.00</b>	<b>7,600.00</b>	<b>44.57</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>7,500.00</b>		
<b>(\$\$)</b>	17,050.00	7,500.00	9,550.00	56.01
<b>+ GST 9.00/9.00% (\$\$)</b>	1,534.50	675.00	859.50	56.01
<b>Nett Amount (\$\$)</b>	<b>18,584.50</b>	<b>8,175.00</b>	<b>10,409.50</b>	<b>56.01</b>

INSPECTION

Date of Assignment:	22/10/2024	
Date Inspected:	23/10/2024	Inspected At: Smc Auto Engineering Works (kaki Bukit) (HQ) 1 KAKI BUKIT AVE 6 #01-01 AUTO BAY Singapore 417883
Estimated Period of Repair:	7.0 days	

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Nov 2024)	
Parts:	N/A	mitsubishi canter 3.0 d feb21er3sden (cbu) (m) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP82H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH SLIDING DOOR	Damaged / Bent	2,200.00 FS	*1,400.00 FS
2	1		*REAR LH SLIDING DOOR SPRING LOCK	Repair	120.00 FS	*- FS
3	1		*REAR LH SLIDING DOOR WOODEN BOARD	Not Necessary	400.00 FS	*- FS
4	1		*REAR LH SLIDING DOOR PANEL LOWER BRACKET	Bent	550.00 FS	*300.00 FS
5	1		*REAR LH CARGO BOX FRONT PANEL	Distorted	1,800.00 FS	*1,200.00 FS
6	1		*REAR LH CARGO BOX INNER METAL PANEL	Distorted	1,400.00 FS	*1,000.00 FS
7	1		*REAR LH CARGO BOX INNER WOODEN BOARD	Cracked	600.00 FS	*500.00 FS
8	1		*REAR LH CARGO BOX INNER SUPPORT METAL PANEL	Bent	400.00 FS	*300.00 FS
9	1		*REAR LH CARGO BOX TOP ALUMINIUM PANEL	Buckled	2,600.00 FS	*1,500.00 FS
10	1		*REAR LH CARGO BOX TOP INNER METAL PANEL	Buckled	1,500.00 FS	*1,000.00 FS
11	1		*REAR LH CORPORATE ADVERTISEMENT & ARTWORK	Necessary	600.00 FS	*250.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					12,170.00	7,450.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	3,000.00	1,000.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTECD AREAS	New	1,800.00	1,000.00
3	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,880.00</b>	<b>2,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >