

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100381/AUA3Q2**Date:** 21/08/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220127162
Claimant Vehicle No : SKX298B **Insured Vehicle No :** SKB5533E
 Date of Loss: 20/10/2024 Nature of Claim: TP Claim No: 0146535489SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX298B**
 Make & Model: MERCEDES-BENZ A180 R17, 1.6 (A) Engine No: 27091030777826
 Reg. Date: 10/12/2015 (Man. Year: 2015) Chassis No: WDD1760422J406097
 Colour: Bronze Odometer: 160255 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,753.40	7,671.30	4,082.10	34.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	2,000.00	1,180.00	37.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,933.40	9,671.30	5,262.10	35.24
Approved Total (Overridden) (S\$)		7,700.00		
Nett Amount (S\$)	14,933.40	7,700.00	7,233.40	48.44
+ Car Rental (7.0 x S\$100.00/day + 9.00% GST) (S\$)		763.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		8,465.18		
Global Sum Settlement (S\$)		8,460.00		

INSPECTION

Date of Assignment: 21/10/2024

Date Inspected: 21/10/2024 Inspected At:

 Premium Carz Services Pte Ltd (HQ)
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki
 Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,328.00 FL	*1,810.00 FL
2	1		*TAILGATE WINDSCREEN GLASS & MOULDING	Shattered	795.00 FL	*795.00 FL
3	1		*TAILGATE LOCK	Damaged	367.00 FL	*367.00 FL
4	1		*TAILGATE WIPER	Cut	65.00 FL	*65.00 FL
5	1		*TAILGATE WIPER MOTOR (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*TAILGATE MERCESES LOGO	Necessary	108.00 FL	*108.00 FL
7	1		*A 180 EMBLEM	Necessary	138.00 FL	*138.00 FL
8	1		*TAILGATE CYCLE & CARRIAGE LOGO	Necessary	98.00 FL	*98.00 FL
9	1		*REAR BUMPER	Deformed	1,590.00 FL	*1,325.00 FL
10	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	55.00 FL	*- FL
11	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	55.00 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Not Necessary	605.00 FL	*- FL
13	1		*REAR BUMPER LOWER PAD	Cut	259.00 FL	*259.00 FL
14	1		*END PANEL	Dented	1,260.00 FL	*1,260.00 FL
15	1		*REAR BUMPER BEAM	Deformed	198.00 FL	*198.00 FL
16	2		*REAR NUMBER PLATE LAMP	Not Necessary	90.00 FL	*- FL
17	1		*EXHAUST HEATER SEAL	Not Necessary	240.00 FL	*- FL
18	1		*FRONT BUMPER	Torn	1,890.00 FL	*1,389.00 FL
19	1		*FRONT BUMPER INNER FOAM	Cracked	145.00 FL	*145.00 FL
20	1		*FRONT FENDER LH (NPA)	Repair	0.00 FL	*- FL
21	10		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
22	10		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
23	2		*FRONT SENSOR	Damaged (1 PCS ONLY)	752.00 FS	*250.00 FS
24	4		*SET REVERSE SENSOR	Damaged (2 PCS ONLY)	1,504.00 FS	*200.00 FS
25	1		*FRONT NUMBER PLATE WITH CASING	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,782.00	8,467.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,028.60	795.70
Total Parts (\$)	11,753.40	7,671.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	100.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS FRONT	New	400.00	200.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS FRONT	New	500.00	250.00
4	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS REAR	New	1,200.00	800.00
5	SPRAY PAINTING ALL AFFECTED PARTS & AREAS REAR	New	800.00	600.00
6	LABOUR REMOVE & REFIT TAILGATE WINDSCREEN	New	180.00	120.00
Gross Labour Cost (\$\$)			3,180.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >