

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIG24100382/KQP3E2**Date:** 11/11/2024REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900112676
<b>Claimant Vehicle No :</b>	SNA4086E	<b>Insured Vehicle No :</b>	GBG3711B
Date of Loss:	19/10/2024	Nature of Claim:	TP
		Claim No:	6154475066SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNA4086E</b>	Engine No:	2ZR2M07449
Make & Model:	TOYOTA NOAH, 1.8 (A)	Chassis No:	ZWR800496024
Reg. Date:	22/06/2021 (Man. Year: 2021)	Odometer:	250517 km
Colour:	Metallic Pearl White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 9 mm	Rear Left Side:	Davanti 9 mm
Front Right Side:	Davanti 9 mm	Rear Right Side:	Davanti 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,854.16	1,249.50	7,604.66	85.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	920.00	830.00	47.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,604.16</b>	<b>2,169.50</b>	<b>8,434.66</b>	<b>79.54</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,604.16</b>	<b>1,700.00</b>	<b>8,904.16</b>	<b>83.97</b>

INSPECTION

Date of Assignment:	22/10/2024	
Date Inspected:	23/10/2024	Inspected At: JD Motorsports Pte Ltd (HQ) 5034 Ang Mo Kio Ind Pk 2, #01-341/343 Singapore 569537
Estimated Period of Repair:	3.0 days	

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILLAMP (LH)	Cut	1,780.70 F	*1,056.20 FL
2	1		*REAR TAILLAMP CHROME MOULDING (LH)	Dented	435.25 F	*311.10 FL
3	1		*REAR BUMPER	Repair	1,339.41 F	*- FL
4	1		*REAR BUMPER SIDE BRACKET (LH)	Serviceable	121.90 F	*- FL
5	1		*REAR BUMPER REFLECTOR (LH)	Serviceable	251.20 F	*- FL
6	1		*REAR FENDER COVER (LH)	Dented / Cracked	344.60 F	*298.70 FL
7	1		*REAR TAILGATE	Repair	1,812.70 F	*- FL
8	1		*REAR TAILGATE CHROME MOULDING	Serviceable	767.80 F	*- FL
9	1		*REAR FENDER INNER PANEL (LH)	Repair	1,350.60 F	*- FL
10	1		*REAR REVERSE CAMERA	Serviceable	450.00 FS	*- FS
11	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,854.16	1,666.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	416.50
Total Parts (S\$)	8,854.16	1,249.50

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO SUPPLY LABOUR AND PARTS TO REPLACE ACCIDENT AFFECTED AREA	New	600.00	300.00
2	TO SUPPLY LABOUR AND PAINTS TO SPRAY ACCIDENT AREA	New	800.00	600.00
3	TO SUPPLY LABOUR TO RE-WIRE REPLACE PARTS	New	150.00	20.00
4	TO SUPPLY LABOUR TO REMOVE AND REFIT REAR WINDSCREEN	New	200.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,750.00</b>	<b>920.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >