

ASS. REC. BY:

REF:

CD
11 / 24100383 / kwaz

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

Trans Cab

of

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

05

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: S/HO 9878J

Yr Regn: 11, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prova

C.G. 1798

Colour M.P. White / Red

A/C: Insured / Std / NI / NA

Sp. Reading 205709

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDK B3FU003092580

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size: F: 195/65R15

R: Wanli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 9

mm

R/Bal. 3

mm

L/Bal. 9

mm

L/Bal. 3

mm

D.O.A. 21/10/24

D.O.I. 22/10/2024

Survey held at

Des. of Damages: Frt / Rear O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/11 21:30 @ 6400r Cab

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Transportation

) S + RS. SI

) Fuel

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Not Withheld
1/ Sep 86400/r

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9878J

AAD2410-073

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

22 OCT 2024

Date of Registration:

SHD9878J

JTDKB3FU003092580

200303878K

TOYOTA

PRIUS GEN 4

21/10/2024

SJQ4541X/II

6/11/2020

PART		LIST	
1	COVER, REAR BUMPER	\$	612.68 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	419.90 ✓
1	COVER, REAR BUMPER, LOWER	\$	27.93 ✓
1	GUARD, REAR BUMPER, CENTER	\$	472.19 ✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	167.48 ✓
1	RETAINER, REAR BUMPER SIDE, RH	\$	167.48 ✓
1	REFLECTOR ASSY, REFLEX, LH	\$	49.25 X
1	REFLECTOR ASSY, REFLEX, RH	\$	49.25 X
1	PANEL SUB-ASSY, QUARTER, LH	\$	1,099.46 X
1	LINER, REAR WHEEL HOUSE, LH	\$	176.09 X
1	DUCT ASSY, QUARTER VENT, LH	\$	93.98 X
1	TROUGH, BACK DOOR OPENING, LH	\$	130.31 X
1	PANEL SUB-ASSY, QUARTER, RH	\$	1,099.46 X
1	LINER, REAR WHEEL HOUSE, RH	\$	176.09 X
1	DUCT ASSY, QUARTER VENT, RH	\$	93.98 X
1	TROUGH, BACK DOOR OPENING, RH	\$	130.31 X
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$	428.19 X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	\$	329.49 X
1	COVER, REAR COMBINATION LAMP, LH	\$	88.41 X
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	428.19 X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	\$	329.49 X
1	COVER, REAR COMBINATION LAMP, RH	\$	88.41 X
1	COVER, FLOOR UNDER, NO.1 LH	\$	220.50 ✓
1	COVER, FLOOR UNDER, NO.2 RH	\$	304.92 X
1	COVER, REAR FLOOR CTR	\$	290.43 ✓
1	PAN, REAR FLOOR	\$	734.90 X
1	BOX, DECK FLOOR, REAR	\$	133.25 X
1	BOX, DECK FLOOR, RH	\$	395.12 X
1	BOX, DECK FLOOR, LH	\$	394.38 X
1	PANEL ASSY, DECK TRIM SIDE, LH	\$	448.98 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2410-073**SHD9878J**

1	PANEL ASSY, DECK TRIM SIDE, RH	\$	PL	448.98	X
1	COVER, DECK TRIM, REAR	\$	SL	159.39	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	BL	824.46	✓
1	PANEL SUB-ASSY, BACK DOOR	\$	BL	1,443.86	✓
1	WEATHERSTRIP, BACK DOOR	\$	ND/DI	469.25	✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	CM	1,156.89	✓
1	BOARD ASSY, BACK DOOR TRIM	\$	SL	326.76	X
1	STAY ASSY, BACK DOOR, LH	\$	SL	305.66	X
1	STAY ASSY, BACK DOOR, RH	\$	SL	305.66	X
1	HINGE ASSY, BACK DOOR, LH	\$	R	77.18	X
1	HINGE ASSY, BACK DOOR, RH	\$	R	77.18	X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	ML	68.88	✓
1	PLATE, BACK DOOR NAME, NO.1	\$	ML	68.88	✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	ML	90.30	✓

TOTAL \$ 15,403.83**25% \$ 3,850.96****\$ 11,552.87****Special Nett**

1SET	PARKING AID	\$	ND	700.00	220SL
1SET	REAR BUMPER CLIP	\$	ML	95.00	60SL
2	WINDSCREEN SEALANT	\$	ML	150.00	80SL
1	WINDSCREEN MOULDING	\$	ML	200.00	✓
1	WINDSCREEN INNER SPONGE SEAL	\$	ML	130.00	60SL
1	REAR TAILGATE STICKER "Trans-Cab"	\$	ML	100.00	30SL
1	REAR TAILGATE STICKER "6555-3333"	\$	ML	100.00	30SL
1	REAR BUMPER PROTECTOR	\$	NSP	180.00	X
2	SEAM SEALANT	\$	NA	250.00	X
1SET	REAR BUMPER RETAINER CLIP	\$	NA	85.00	X
1	REAR NUMBER PLATE WITH HOLDER	\$	ND	140.00	45SL
1	FENDER LINER CLIP	\$	NA	65.00	X
1	END PANEL TRIM CLIP	\$	NA	65.00	X

TOTAL \$ 2,260.00**TOTAL PARTS \$ 13,812.87****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 180L

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2410-073**SHD9878J**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	8001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	801
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	501
Towing Fees	\$	150.00	501
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	11001
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 220.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	nn 380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9878J

AAD2410-073

TOTAL	\$	8,440.00
--------------	-----------	-----------------

Over All Total	\$	22,252.87
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days

~~09 DAYS~~

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: