10/29/24, 9:05 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI24100384/ENP3E2

Date: 29/10/2024

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: CDMPG24002736

Claimant Vehicle SHD6781Z Insured Vehicle No : SGZ4011Y

Date of Loss: 21/10/2024 Nature of Claim: TP Claim No: CDMPG24002736

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD6781Z

 Make & Model:
 MERCEDES-BENZ E220 BLUETEC, 2.1 D (A)
 Engine No:
 65192433223143

 Reg. Date:
 08/04/2016 (Man. Year: 2015)
 Chassis No:
 WDD2120012B308922

Colour: White Odometer: 1093482 km

Engine Capacity: 2143 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R16 Rear Tyre Size: 225/55 R16
Front Left Side: DURATURN 5 mm
Front Right Side: DURATURN 5 mm
Rear Right Side: DURATURN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,901.25	1,451.25	1,450.00	49.98
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,080.00	870.00	210.00	19.44
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,981.25	2,321.25	1,660.00	41.70
	Approved Total (Overridden) (S\$)		1,850.00		
	(S\$)	3,981.25	1,850.00	2,131.25	53.53
	+ GST 9.00/9.00% (S\$)	358.31	166.50	191.81	53.53
	Nett Amount (S\$)	4,339.56	2,016.50	2,323.06	53.53

INSPECTION

Date of Assignment: 22/10/2024

Date Inspected: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive

59 Loyang Drive Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/29/24, 9:05 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Oct 2024)

Parts: 143 MERCEDES-BENZ E220 BLUETEC 2.1 D (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD6781Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	1,510.00 FL	*1,510.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
3	1		*REAR BUMPER UNDER COVER	Cut	325.00 FL	*325.00 FL
4	1		*REAR BUMPER BEAM	Not Necessary	1,150.00 FL	*- FL
5	2		*REAR BUMPER BRACKET LOWER LH / RH	Not Necessary	270.00 FL	*- FL
6	1		*REVERSE SENSOR	Not Necessary	380.00 FS	*- FS
7	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 FN
F=Fra	ınchise	part. S=SpcN	lett. L=ListItemDisc. N=NettItemDisc.	_		
				Sub Total (S\$)	3,725.00	1,925.00
			- List Item Discount on	L Items 25.00/25.00% (S\$)	823.75	468.75
			- Nett Item Discount or	- Nett Item Discount on N Items 0.00/10.00% (S\$)		5.00
				Total Parts (S\$)	2,901.25	1,451.25

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	500.00	400.00
2	SPRAY PAINT	New	500.00	450.00
3	REMOVE / REFIX REVERSE SENSOR	New	80.00	20.00
		Gross Labour Cost (S\$)	1,080.00	870.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >