



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: ASTER QUEK

Ref: CS/INC24060228/Aqh3e2(N)

Date: 25/02/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 6832L	Veh. Inspected	GBK 1677J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1282798-002	Excess (\$)	0.00
Assign From	ASTER QUEK	Assign Date	25/06/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTFAT35Y40K214660	Colour	SILVER
Odometer	184804 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/75 R15	YOKOHAMA	6 mm
L/H Front Tyre	175/75 R15	YOKOHAMA	6 mm
R/H Rear Tyre	155 R12C	FALKEN	6 mm
L/H Rear Tyre	155 R12C	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/06/2024	Inspect Date / Time	25/06/2024 (11:40 AM)
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days