

REF:

CS/SMR24100386/Anp3 (SLT 3714G)

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estin: ~~Estin~~ \_\_\_\_\_  
 OD / ~~TP~~ / TP RES / CD RES / EVA / INV / MV  
 To in ~~Vehicle~~ No: \_\_\_\_\_  
 at VV ~~Estin~~ / m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Vek: \_\_\_\_\_  
 (Policy Condition)

N/S	O/S

Remark: Tlevah had commenced its  
 repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repair: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLT 3714G Yr Regn: 2017 / Oct.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel Hybrid C.D. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 176658 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 2u31255666Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil AS/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front

R/Bal. 06 mmL/Bal. 06 mm

D.O.A. \_\_\_\_\_

Survey held at

Des. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 06 mmL/Bal. 06 mmD.O.A. 17/10/24HD Perfect

Date / Time

Action / Instruction

TP 1st Lap.COE Expiry

Estimate given during: Yes ( ✓ )  
 1st Survey: No ( )

MV: 46KPV: 18.3K

Nett.

Adrian confirmed lump sum \$5300 and 4 days  
 (red, \$5305.28, 50%)

318D

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

S + RS. \$1

Photos

Others

1)

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Inve (\$

Report Format:

A. from 2011.1.1. P. 10




# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT  
AUTOWORK PTE LTD

DATE : 15.10.2024

TO : MS FIRST CAP MOTOR CLAIMS DEPTS  
VEHICLE NO : SLT3714G  
MODEL : HONDA VEZEL  
DATE OF ACCIDENT : 09.10.2024  
TIME OF ACCIDENT : 15:05 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	GRILLE LOGO GARNISH <i>lt</i>	1	\$ 485.00	\$ 485.00
2	HEADLAMP <i>lt KAA</i>	2	\$ 1,958.40	\$ 3,916.80
3	FRONT FENDER ARCD GARNISH LH <i>new</i>	1	\$ 195.00	\$ 195.00
4	FRONT WIPER PANEL GARNISH <i>new</i>	1	\$ 492.30	\$ 492.30
5	FRONT WIPER BLADE <i>new</i>	2	\$ 98.50	\$ 197.00
6	FRONT WINDSCREED GLASS <i>lt</i>	1	\$ 1,582.00	\$ 1,582.00
7	FRONT WINDSCREED GLASS MOULDING <i>new</i>	1	\$ 295.00	\$ 295.00
8	SIDE MIRROR LH <i>Repair</i>	1	\$ 841.60	\$ 841.60
9	FRONT DOOR OUTER MOULDING LH <i>3411</i>	1	\$ 87.00	\$ 87.00
10	FRONT DOOR BLACK STICKER LH	1	\$ 95.00	\$ 95.00
11	FRONT DOOR WINDOR GLASS LH <i>lt</i>	1	\$ 486.30	\$ 486.30
12	REAR DOOR WINDOR GLASS LH <i>lt</i>	1	\$ 538.60	\$ 538.60
13	REAR DOOR OUTER MOULDING LH <i>new</i>	1	\$ 95.00	\$ 95.00

TOTAL PRICE \$ 9,306.60  
LESS 20% \$ 1,861.32  
SUB TOTAL PRICE \$ 7,445.28

## SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT WIPER PANEL GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00

TOTAL \$ 30.00



TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SLT3714G**  
MODEL : **HONDA VEZEL**  
DATE OF ACCIDENT : 09.10.2024  
TIME OF ACCIDENT : 15:05 HOURS

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	100
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1000
3	REMOVE AND REFIX FRONT AND REAR DOOR WINDOR GLASS LH	\$ 180.00	80
4	REMOVE AND REFIX FRONT WINDSCREEN GLASS	\$ 150.00	120

**TOTAL \$ 3,130.00**

TOTAL PARTS COST : \$ 7,475.28  
TOTAL LABOUR COST : \$ 3,130.00  
TOTAL REPAIR COST : \$ 10,605.28

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
IRENE  
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adrian L  
2/S 17/10/24

04 Days