



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMD 3681P

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SIDE MIRROR HOUSING WITH MOTOR LH	CRACKED	\$1,807.10	\$1,807.10
1	SIDE MIRROR LAMP LH	NOT NECESSARY	\$94.70	\$0.00
1	SIDE MIRROR OUTER COVER -LH	CUT	\$184.00	\$184.00
	LESS 25.00% DISCOUNT		(\$521.45)	(\$497.78)
			\$1,564.35	\$1,493.32
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO KNOCK OUT DENTS ON DOOR REMOVE REFIT DOOR TRIM TO REPLACE SIDE MIRROR ASSY LH		\$450.00	\$150.00
	TO RESPRAY PAINT ON SIDE MIRROR COVER ,DOOR LH		\$350.00	\$280.00
	TO CHECK WIRING		\$30.00	\$20.00
			\$830.00	\$450.00
GRAND TOTAL			\$2,394.35	\$1,943.32
RECOMMENDED COST OF REPAIRS				\$1,943.32
Report Ref No: CD/FCI24100388/Uma3q2				

**CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.