

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

VEHICLE NO : GBK 6028 A

CHASSIS NO : JN1YAAM20Z0001055

MAKE / MODEL : NISSAN NV200

ACCIDENT DATE : 18.10.2024

TP INC
Veren.

NO	DESCRIPTION	QTY	AMOUNT (\$\$)
LIST ITEMS			
1	Front bumper <i>Rehnd</i>	1	\$ 643.32
2	Front bumper LH top cover <i>Rehnd</i>	1	\$ 395.16
3	Front bumper side holder @ \$25.20 <i>new</i>	2	\$ 50.40
4	Front bumper clips <i>new</i>	1	\$ 72.00
5	Front grille <i>new</i>	1	\$ 462.24
6	Front grille logo <i>new</i>	1	\$ 98.28
7	Front LH headlamp <i>at</i>	1	\$ 576.00
8	Front LH fender <i>Dented</i>	1	\$ 598 737.64
9	Front LH fender inner shield <i>Rehnd</i>	1	\$ 25.80
10	Front LH fender inner shield clips <i>in</i>	1	\$ 4.32
11	Front LH fender signal lamp <i>cracked</i>	1	\$ 82.92
12	Front LH fender quater glass <i>shattered</i>	1	\$ 397.68
13	Front LH fender quater glass lower cover <i>Missing</i>	1	\$ 30.84
14	Front LH door <i>Dishled</i>	1	\$ 1319 1666.92
15	Front LH door glass <i>at</i>	1	\$ 640 1254.48
16	Front LH door glass outer moulding <i>at</i>	1	\$ 187.08
17	Front LH door glass channel <i>new</i>	1	\$ 69.36
18	Front LH door outer handle <i>at</i>	1	\$ 88.56
19	Front LH door top hinge <i>new new</i>	1	\$ 78.24
20	Front LH door bottom hinge <i>new new</i>	1	\$ 78.24
21	Front LH door stopper <i>new</i>	1	\$ 26.52
22	Front LH door company <i>in</i>	1	\$ 36.00
23	Front LH door inner rubber <i>?</i>	1	\$ 247.20
24	Front LH door side mirror housing <i>Dishled</i>	1	\$ 473.52
25	Front LH door side mirror top side mirror <i>new</i>	1	\$ 120.00
26	Front LH door front pillar <i>Rein</i>	1	\$ 2022.36
27	Front LH tyre <i>Punctured</i>	1	\$ 420.00
28	Front LH rim <i>Best</i>	1	\$ 265.80
29	Front LH shock absorber <i>Best</i>	1	\$ 247.64
30	Front LH lower arm <i>Best</i>	1	\$ 303.72
31	Front LH knuckle arm <i>Best</i>	1	\$ 518.64
32	Front LH knuckle arm bearing <i>Best</i>	1	\$ 447.72
33	Front LH linkage <i>new</i>	1	\$ 45.84
34	Front LH drive shaft <i>new</i>	1	\$ 1195.44
35	Front LH door inner board <i>cracked</i>	1	\$ 508 785.28
36	Front windscreen <i>cracked</i>	1	\$ 1351 1728.84
37	Steering rack assy <i>new Best</i>	1	\$ 1815 2641.32
38	Front windscreen LH side garnish <i>new</i>	1	\$ 65.52
39	Front wiper garnish <i>new</i>	1	\$ 386.16

18,977

11021.72 SN: 180
9919.54

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

VEHICLE NO : GBK 6028 A

MAKE / MODEL : NISSAN NV200

CHASSIS NO : JN1YAAM20Z0001055

ACCIDENT DATE : 18.10.2024

NO	DESCRIPTION	QTY	AMOUNT (S\$)
LABOUR COST			
1	Towing fee	1	\$ 150.00
2	To supply front windscreen sealant	1	\$ 50.00
3	Remove + reinstall front windscreen	1	\$ 200.00
4	Remove + reinstall front LH suspension	1	\$ 600.00
5	Remove + reinstall deskboard	1	\$ 400.00
6	Remove + reinstall door glass	1	\$ 150.00
7	Remove, replace + repair consistent to the accident	1	\$ 1800.00
8	Respray painting	1	\$ 1500.00
9	Tuff kote	1	\$ 100.00
10	To check wheel alignment	1	\$ 100.00

TOTAL \$ 5050.00

GRAND TOTAL \$

24,027.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adrian L
2/s 23/10/24.
10 Days.

total 12629.54
2/s: 10.1K

10.1K.