



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100391/Unh3e2
75 BRAS BASAH ROAD	Date:	04/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SME 3108Z	Veh. Inspected	SNH 9893Y
Policy No.	-	Coverage	0
Claim No.	MT/1300655-001	Excess	\$0.00
Assign From	EILEEN LEE	Assign Date	23/10/2024

### 2. Vehicle Details

Make & Model	TOYOTA LEXUS ES300H (A)	C.C	2494
Engine No.	2AR1886146	Year of Reg.	25/01/2018
Chassis No.	JTHBW1GGX02182468	Colour	SILVER
Odometer	61466 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55R17	HANKOOK	6
L/H Front Tyre	215/55R17	HANKOOK	6
R/H Rear Tyre	215/55R17	HANKOOK	6
L/H Rear Tyre	215/55R17	HANKOOK	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	19/10/2024	Inspection Date	28/10/2024 (09:41)
Survey held at	LLM AUTO LEASING PTE LTD C/O BLUWEL AUTOMOTIVE SERVICE PTE LTD - 1 KAKI BUKIT AVENUE 6, #01-55, AUTOBAY, S(417883)		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days