

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24100395/UQP3E2**Date:** 05/12/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30003445622		
Claimant Vehicle No :	SLW4545E	Insured Vehicle No :	YN6623T		
Date of Loss:	21/10/2024	Nature of Claim:	TP	Claim No:	377458

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW4545E		
Make & Model:	TOYOTA YARIS CROSS, 1.5 HYBRID ACTIVE (2WD) (A)	Engine No:	M15AY474764
Reg. Date:	30/01/2023 (Man. Year: 2022)	Chassis No:	JTDKBAB330L011380
Colour:	Red	Odometer:	161433 km
Engine Capacity:	1490 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,994.80	2,287.42	1,707.38	42.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	720.00	1,400.00	66.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,114.80	3,007.42	3,107.38	50.82
+ GST 9.00/9.00% (S\$)	550.33	270.67	279.66	50.82
Nett Amount (S\$)	6,665.13	3,278.09	3,387.04	50.82

INSPECTION

Date of Assignment:	23/10/2024		
Date Inspected:	25/10/2024	Inspected At:	Automobile Integrated Management Pte Ltd (HQ) 3021A Ubi Road 1, #01-42 Singapore 408715
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$3,007.43

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2024)
Parts:	M1-SUV	TOYOTA YARIS CROSS 1.5 HYBRID ACTIVE (2WD) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW4545E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,208.30 FL	*- FL
2	1		*FRONT FENDER LH	Dented / Bent	1,081.00 FL	*1,081.00 FL
3	1		*FRONT FENDER PROTECTOR (SCRATCHED)	Not Consistent With The Impact	291.20 FL	*- FL
4	1		*FRONT HEADLAMP LH	Holder Cracked	1,968.90 FL	*1,968.90 FL
5	1		*FRONT BUMPER	Not Necessary	643.20 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	133.80 FL	*- FL
					Sub Total (\$\$)	5,326.40 3,049.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,331.60 762.48
					Total Parts (\$\$)	3,994.80 2,287.42

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL WIRING	New	120.00	20.00
2	TO RESPRAY PAINTING AND ETC	New	1,000.00	400.00
3	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	1,000.00	300.00
Gross Labour Cost (\$)			2,120.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >