



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLP 5651L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DENTED	\$1,600.00	\$1,600.00
1	REAR BUMPER LOWER DIFFUSER	CUT	\$520.00	\$520.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	\$680.00	\$0.00
2	REAR BUMPER REFLECTOR LAMP LH & RH	NOT NECESSARY	\$220.00	\$0.00
2	REAR BUMPER SIDE RETAINER LH & RH	BROKEN	\$280.00	\$280.00
1	REAR BUMPER 718 BOXSTER EMBLEM	NECESSARY	\$105.00	\$105.00
1	PORSCHE LOGO EMBLEM	NECESSARY	\$155.00	\$155.00
2	TAIL LAMP LH & RH	BROKEN	\$2,300.00	\$2,044.00
2	TAIL LAMP LOWER BRACKET HOLDER LH & RH	NOT NECESSARY	\$580.00	\$0.00
1	BOOTLID INNER LOCK	NOT NECESSARY	\$480.00	\$0.00
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	\$380.00	\$0.00
1	REAR END PANEL	NOT NECESSARY	\$700.00	\$0.00
1	END PANEL TOP GARNISH	NOT NECESSARY	\$375.00	\$0.00
1	REAR TOP SPOILER TRUNK	NOT NECESSARY	\$650.00	\$0.00
2	REAR FENDER INNER TRIM BOARD LH & RH	NOT NECESSARY	\$1,750.00	\$0.00
1	REAR END PANEL HEAT SHIELD GARNISH ASSY	DENTED	\$800.00	\$555.10
1	EXHAUST MUFFLER ASSY	NOT NECESSARY	\$4,000.00	\$0.00
	<b>LESS 5.00 / 10.00% DISCOUNT</b>		(\$778.75)	(\$525.91)
			\$14,796.25	\$4,733.19

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR CAR PLATE (SN)	BROKEN	\$40.00	\$40.00
1	REVERSE SENSOR (SN)	SHORTED	\$250.00	\$200.00
1	REVERSE CAMERA (SN)	NOT NECESSARY	\$350.00	\$0.00
1	END PANEL SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
			\$720.00	\$240.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS		\$800.00	\$300.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECKING WIRING AND REWIRE		\$50.00	\$50.00
	TO REMOVE & REFIX REAR SENSOR		\$80.00	\$50.00
	TO REMOVE AND REINSTALL EXHAUST ASSY	NOT NECESSARY	\$120.00	\$0.00
	TO ANTI-RUST		\$80.00	\$30.00
	TO CLEAR & RESET MODULE FAULT CODES		\$250.00	\$150.00
	TO REMOVE AND REINSTALL BOOTLID COMPONENTS	NOT NECESSARY	\$80.00	\$0.00
	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	NOT NECESSARY	\$80.00	\$0.00
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS		\$800.00	\$250.00
			\$2,340.00	\$830.00
<b>GRAND TOTAL</b>			<b>\$17,856.25</b>	<b>\$5,803.19</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$4,650.00</b>
Report Ref No: CS/AGI24100401/Enp3m4				

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.