



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGC 7391B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SUNDRIES (SN)	NECESSARY	15.00	15.00
1	OIL PAN (SN)	CRACKED	553.54	553.54
1	ELASTOMERIC MOLDED SEAL (SN)	NOT NECESSARY	56.39	-
2	TRANSMISSION FLUID (SN)	NECESSARY	480.70	480.70
1	COVER, ENGINE COMP. LOWER (SN)	CRACKED	224.17	224.17
1	COVER F ENGINE COMP. BM (SN)	CRACKED	281.56	281.56
1	AUTOMATIC TRANSMISSION (SN)	NOT NECESSARY	21,271.67	-
1	BUMPER FRONT UNDERNEATH COVER (SN) (ADDITIONAL)	CRACKED	265.82	265.82
1	MOUNT JACK TO INTEGRAL CARRIER (SN) (ADDITIONAL)	DISTORTED	45.93	45.93
10	SCREW W RND. HEXAL. HEAD (SN) (ADDITIONAL)	NECESSARY	52.50	52.50
			23,247.28	1,919.22
	<b><u>LABOUR</u></b>			
	REMOVE CARRIAGE ASSY FROM FRAME, IMPACT. REPLACE AND ASSEMBLE.		2,400.00	1,920.00
	TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT.		540.00	540.00
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO.		380.00	380.00
	TOWING.		150.00	150.00
			3,470.00	2,990.00
	<b>GRAND TOTAL</b>		<b>26,717.28</b>	<b>4,909.22</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>4,909.22</b>
	<b>LESS EXCESS</b>			<b>-700.00</b>
	<b>NETT LIABILITY</b>			<b>4,209.22</b>

Report Ref No. CS/GAI24100402/Tnp3m4(N)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.