



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SCY 8777Y

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRY (SN)	NECESSARY	\$100.00	\$50.00
1	SOLAR FILM (SN)	NECESSARY	\$350.00	\$350.00
1	NO PLATE (SN)	BENT	\$80.00	\$80.00
1	JOINT PANEL SEALANT (SN)	NECESSARY	\$200.00	\$200.00
1	LAMP UNIT, RR FOG (SN)	SERVICEABLE	\$54.00	\$0.00
1	LAMP ASSY, RR COMB, R (SN)	NOT NECESSARY	\$645.60	\$0.00
1	LAMP ASSY, RR COMB, L (SN)	NOT NECESSARY	\$645.60	\$0.00
1	REFLECTOR ASSY, REAR (SN)	NOT NECESSARY	\$24.30	\$0.00
1	REFLECTOR ASSY, REAR (SN)	NOT NECESSARY	\$68.60	\$0.00
2	LAMP ASSY, LICENSE (SN)	SERVICEABLE	\$229.20	\$0.00
1	CAMERA ASSY, BACK (SN)	NOT NECESSARY	\$1,947.25	\$0.00
1	PANEL COMP, BACK (SN)	BENT	\$1,410.30	\$410.30
1	BUMPER, REAR (SN)	DEFORMED	\$953.30	\$953.30
1	COVER, LICENSE LAMP (SN)	CRACKED	\$158.25	\$58.25
1	HOLDER, RR BUMPER SIDE, R (SN)	NECESSARY	\$8.25	\$8.25
1	HOLDER, RR BUMPER SIDE, L (SN)	NOT NECESSARY	\$8.25	\$0.00
1	COVER, RR BUMPER SIDE, R (SN)	CRACKED	\$35.90	\$35.90
1	COVER, RR BUMPER SIDE, L (SN)	SERVICEABLE	\$35.90	\$0.00
10	CLIP (SN)	NECESSARY	\$29.00	\$29.00
1	TRIM, TAIL END (SN)	CRACKED	\$177.25	\$77.25
5	CLIP (SN)	NECESSARY	\$11.25	\$11.25
2	OUTLET COMP, VENTILATOR (SN)	CRACKED	\$134.50	\$54.50
1	EMBLEM, MARK S (SN)	NECESSARY	\$36.20	\$36.20
1	EMBLEM (SWIFT) (SN)	NECESSARY	\$71.70	\$31.70
1	EMBLEM, RR, HYBRID (SN)	NECESSARY	\$26.55	\$26.55
1	GLASS COMP, BACK DOOR WINDOW (SN)	NECESSARY	\$1,724.00	\$711.95
1	GARNISH, BACK DR LWR (SN)	NECESSARY	\$63.70	\$23.70
1	WEATHERSTRIP, BACK DOOR OPNG (SN)	CUT	\$210.25	\$80.25
1	LATCH COMP, BACK DOOR (SN)	SERVICEABLE	\$22.95	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	PANEL ASSY, BACK DOOR (SN)	BENT	\$983.45	\$983.45
4	BRACKET, AUTO BRAKE (SN)	CRACKED	\$325.80	\$325.80
			\$10,771.30	\$4,537.60

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	DRILL HOLE AND INSTALL REVERSE SENSOR	NOT NECESSARY	\$162.00	\$162.00
	CHECK WIRING SYSTEM		\$162.00	\$162.00
	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR		\$648.00	\$324.00
	REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE		\$486.00	\$486.00
	TO RESET ECU AND REPROGRAMME		\$162.00	\$162.00
	TO CONDUCT ADJUSTMENT ON BLIND SPOT SENSOR		\$162.00	\$0.00
	REPLACE TAILGATE GLASS		\$486.00	\$486.00
	REPLACE ACC DAMAGED PARTS		\$3,888.00	\$2,592.00
	RESPRAY ACC AFFECTED AREAS		\$3,216.51	\$2,680.00
				\$9,372.51

GRAND TOTAL			\$20,143.81	\$11,591.60
RECOMMENDED COST OF REPAIRS				\$11,591.60
Report Ref No: CS/FCI24100404/Rqp3e2				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.