

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III24100407/RNP3M4**Date:** 04/11/2024REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D24MCV0006082		
Claimant Vehicle No :	SMB3052R	Insured Vehicle No :	GBC2E		
Date of Loss:	12/10/2024	Nature of Claim:	TP	Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB3052R	Engine No:	50334690703468
Make & Model:	MAN NL320F (A22), 10.5 D (A)	Chassis No:	WMAA22ZZ0D7001810
Reg. Date:	02/05/2013 (Man. Year: 2012)	Odometer:	658397 km
Colour:	Green		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	579.84	579.84	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	588.00	588.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,167.84	1,167.84	0.00	0.00
+ GST 9.00/9.00% (S\$)	105.11	105.11	0.00	0.00
Nett Amount (S\$)	1,272.95	1,272.95	0.00	0.00

INSPECTION

Date of Assignment:	23/10/2024	
Date Inspected:	23/10/2024	Inspected At: SBS TRANSIT PTE LTD (ULU PANDAN) (HQ) ULU PANDAN WS, 1 BUSINESS PARK DRIVE, SINGAPORE 608506
Estimated Period of Repair:	1.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Nov 2024)	
Parts:	N/A	MAN NL320F (A22) 10.5 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMB3052R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER .FRP HEADLAMP.O/S.FRONT FRP	Cracked	339.00 F	*339.00 F
2	1		*HEADLAMP.AUXILIARY W/FLASHER.RH	Scratched	240.84 F	*240.84 F
F=Franchise part.						
Total Parts (S\$)					579.84	579.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE / REPLACE / REPAIR DAMAGED PARTS BY WORKSHOP	New	188.00	188.00
2	TO REMOVE / REPLACE / REPAIR DAMAGED PARTS BY CONTRACTOR	New	400.00	400.00
3	TO REMOVE/ REPLACE/ REPAIR DAMAGED ADVERTISEMENT PANEL (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			588.00	588.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >