



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AXALT LAW LLC	Ref:	CS/LAW24100408/Uqp3e2
66 TANNERY LANE, #01-04I, SINDO BUILDING	Date:	07/11/2024
SINGAPORE 347805	Code:	C24A0008

1. Policy Particulars :- THIRD PARTY CLAIM (PHYSICAL REINSPECTION)

Insured Veh.	SMD 1053R	Veh. Inspected	SLU 2336R
Policy No.	-	Coverage	0
Claim No.	ALL.B1.2401392.IG	Excess	\$0.00
Assign From	IGENE	Assign Date	21/10/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA AXIO HYBRID	C.C	1496
Engine No.	1NZR505471	Year of Reg.	27/11/2017
Chassis No.	NKE1657145318	Colour	BLACK
Odometer	451009 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60R15	RYDANZ	6
L/H Front Tyre	185/60R15	RYDANZ	6
R/H Rear Tyre	195/60R15	DUNLOP	6
L/H Rear Tyre	195/60R15	DUNLOP	6

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	03/04/2024	Inspection Date	28/10/2024
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL - 1 KAKI BUKIT AVENUE 6, #01-55, AUTOBAY, S(417883)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days