



Inspection Services Pte Ltd

Vehicle Survey Report

Insurer:	Direct Asia Insurance (Singapore) Pte. Ltd.	Claim Number:	137345/FA
Workshop:	Bluwel Automotive Service Pte Ltd	Claim Type:	PRI
Vehicle No:	SLU 2336R	Vehicle Make & Model:	Toyota Corolla Axio Hybrid 1.5 CVT
Engine Capacity:	1,496 cc	Colour:	Black
Registration Year:	27/11/2017	Vehicle Mileage:	408393 km
Chassis No:	NKE1657145318	Engine No:	1NZR505471
Economic Repair Limit	Market Value: S\$52,000.00 PARF/COE Rebate: S\$18,753.00 Repair Limit: S\$33,247.00	Part by Part Repair or Lump Sum Repair:	Part by part
Workshop Estimate Cost:	None Given	Surveyor Estimated Repair Cost (Excluding GST):	\$6,737.00
Days to Repair:	7 days	OD Excess Applicable:	NA
Assessor:	Mohamad Affandi	Date & Time of Assessment:	09/04/2024, 1040 hrs
NIMA Protocol:	X	1 st Inspection was done with the dismantling of hidden parts	
		1 st Inspection was done without the dismantling of hidden parts	
		2 nd Inspection was done where hidden damaged parts were dismantled in the presence of the Surveyor and not before	
		2 nd Inspection was done where hidden damaged parts were dismantled not in the presence of the Surveyor	

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155


Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd

AREA OF DAMAGED

The vehicle sustained damage on the front and rear portions.



REMARKS

Our surveyor has recommended that the repair cost part by part basis at S\$6,737.00 with approximately 07 days of repair. However, no finalisation was agreed with the repairer.

Please take note that repairer did not provide us the estimate and they only requested us to do the pre-repair survey.

The survey was conducted strictly on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R

DAMAGE PHOTOGRAPHS



ACCIDENT AREA



ACCIDENT AREA

AJAX

Inspection Services Pte Ltd



ODOMETER



ODOMETER

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R

AJAX

Inspection Services Pte Ltd



REAR BUMPER DEFORMED



BOOTLID BUCKLED

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R

AJAX

Inspection Services Pte Ltd



BOOTLID BUCKLED



BOOTLID OUTER CHROME GARNISH CRACKED

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155


Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd



REAR BUMPER SIDE RETAINER CRACKED



TAILLAMP CRACKED

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd



TAILLAMP CRACKED



BOOTLID HINGE BENT

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd



BOOTLID HINGE BENT



BOOTLID LOCK DISTORTED

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd



BOOTLID WEATHERSTRIP CUT



REAR BUMPER RUBBER MAT DEFORMED

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R

AJAX

Inspection Services Pte Ltd



FRONT BUMPER REPAIR



FRONT BUMPER REPAIR

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R

AJAX

Inspection Services Pte Ltd



DISMANTLING



REAR END PANEL BUCKLED

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd



TAILLAMP PANEL LH BUCKLED



REAR FENDER LH REPAIR

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd



REAR END PANEL INNER TRIM DEFORMED



REAR END PANEL INNER TRIM DEFORMED

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd



REAR FENDER INNER TRIM CRACKED



REAR FENDER INNER TRIM CRACKED

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd



REAR BUMPER DEFORMED



REAR REVERSE SENSOR DISTORTED

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd



REAR REVERSE SENSOR DISTORTED



REAR BUMPER REFLECTOR CRACKED/ MISSING

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



TAILLAMP CRACKED



TAILLAMP CRACKED

AJAX

Inspection Services Pte Ltd

AFTER PAINT



AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R

AJAX

Inspection Services Pte Ltd



AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd

No.	Qty	Description of Parts	Condition	Our Recommendation S\$
List Items				
1	1	Bootlid	Buckled	1,075.00
2	1	Bootlid outer chrome garnish	Cracked	385.00
3	1	Bootlid lock	Distorted	190.00
4	1	Bootlid weatherstrip	Cut	187.00
5	2	Bootlid hinges	Bent	253.00
6	2	Taillamp	Cracked	1,544.00
7	1	Rear fender LH	Repair	--
8	1	Rear bumper	Deformed	684.00
9	2	Rear bumper side retainer	Cracked	195.00
10	1	Rear bumper reflector	Cracked	160.00
11	1	Rear fender inner trim LH	Cracked	450.00
12	1	Rear end panel	Buckled	798.00
13	1	Rear end panel inner trim	Deformed	295.00
14	1	Taillamp panel LH	Buckled	220.00
15	1	Front bumper	Repair	--
Sub Total:				6,436.00
Discount (less 25%):				1,609.00
				4,827.00

Special Nett Items				
1	1	Rear bumper black mat	Deformed	50.00
2	1	Rear reverse sensor	Distorted	200.00
3	1	Rear bumper clips	Necessary	30.00
4	1	Rear fender inner trim clips	Necessary	30.00
Sub Total:				310.00
Total Parts Price:				5,137.00

Labour Cost		
1	Labour for panel beating etc	800.00

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd

2	Spray paint	800.00
Sub Total:		1,600.00
Grand Total:		6,737.00

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R



Inspection Services Pte Ltd

Repair Cost Summary			
Workshop Assessment Excluding GST		AJAX Inspection Services Pte Ltd Assessment Excluding GST	
Labour:	\$0.00	Labour:	\$1,600.00
Parts:	\$0.00	Parts:	\$5,137.00
Total:	\$0.00	Total:	\$6,737.00
The repairs will take 07 working days to complete.			

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08 Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 684 99155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No: 201318067R