

Date: 24/6/2024
Vehicle No: SMU6176Y
Model: VOLVO XC40
Chassis: YV1ZACADL2283554
Reg.Year: 2020

Third Party Insurer: MS FIRST CAPITAL
Third Party Veh No: SHB223T
Date of Accident: 16/6/2024
Estimator: JONATHAN
Surveyor:

Not Withheld
Running B4 pain
4 days
11 hrs @ 6900h

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RR BOOT <i>2312</i>			\$ <i>By</i> 2,700.00
	RR BOOTLID EMBLEM (VOLVO)			\$ <i>M</i> 146.00
	RR BOOTLID EMBLEM (XC 40)			\$ <i>M</i> 146.00
	RR BOOTLID EMBLEM (T4)			\$ <i>M</i> 137.00
	RR BUMPER - COMPLETE		<i>Bul/Ad</i>	\$ 1,995.00
	RR ULTRASONIC SENSOR			\$ <i>mit</i> 349.00
	RR BUMPER REINFORCEMENT <i>1280</i>			\$ <i>By</i> 1,440.00
SUB TOTAL				\$ 6,913.00
Less 10%				-\$ 691.30
PARTS TOTAL				\$ 6,221.70

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	RR BUMPER CLIPS			\$ <i>M</i> 50.00
	RR W/SCREEN SEALANT			\$ <i>M</i> 100.00
S/N TOTAL				\$ 150.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix RR affected areas

\$ *500/* 800.00 *400/*

To perform wiring checks on electrical systems

\$ 30.00 *20/*

To remove, putty, repair, sand and respray affected areas

\$ *560/* 600.00 *440/*

To remove, replace & refix bumper sensors

\$ 30.00 ✓

To remove, replace & reinstall Bootlid inner mechansim

\$ 30.00 ✓

To remove, refix & replace RR Windscreen

\$ 120.00 ✓

To perform Adas Checks, Calibration & Programming

\$ 200.00 *80/*

LABOUR TOTAL \$ 1,810.00

JONATHAN

TOTAL \$ 8,181.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

Signature:

Date:



Date: 3/7/2024
Vehicle No: SMU6176Y
Model: VOLVO XC40
Chassis: YV1ZACADL2283554
Reg.Year: 2020

Third Party Insurer: MS FIRST CAPITAL
Third Party Veh No: SHB223T
Date of Accident: 45459

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	RR BOOTLID SWITCH OPENING HANDLE <i>682</i>			<i>Ref</i> \$780.00
2	RR LH BUMPER TOP MOLDING COVER			<i>my car Ref</i> \$420.00
SUB TOTAL				\$1,200.00
LESS 10%				-\$120.00
PARTS TOTAL				\$1,080.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
S/N TOTAL				\$0.00

SUPPLEMENTARY

LABOUR CHARGES:

TO RESPRAY RR LH BUMPER TOP MOLDING COVER

hour \$150.00 *100%*

LABOUR TOTAL \$150.00

VIC / TING AN TOTAL \$1,230.00

SNP: PARTS: 1080
Labour: 150
total: 1230

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9219 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

