1/17/25, 11:19 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24100416/UMA3Q2

Date: 17/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0004186_02

Claimant Vehicle GBE7525G Insured Vehicle No: SMV6556D

No:

Date of Loss: 07/10/2024 Nature of Claim: TP Claim No: MFL2024D0012626

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE7525G**

TOYOTA HIACE, 3.0 D TURBO 5DR (M) Make & Model: Engine No: 1KD2595033

Reg. Date: 21/03/2016 (Man. Year: 2016) Chassis No: JTFHT02P100191181

Colour: White Odometer: 173470 km

Engine Capacity: 2982 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Engine Modification: No Handbrake (Serviceable): Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15 Front Left Side: Rear Left Side: Austone 6 mm Austone 6 mm Front Right Side: Austone 6 mm Rear Right Side: Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,894.00	2,869.42	3,024.58	51.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,340.00	660.00	33.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,894.00	4,209.42	3,684.58	46.68
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	7,894.00	3,300.00	4,594.00	58.20
+ Loss of Use (3.0 x \$	S\$80.00/day) (S\$)	240.00		
+ Doo	c/Search Fee (S\$)	27.25		
1	Nett Liability (S\$)	3,567.25		
Global Sun	n Settlement (S\$)	3,560.00		

INSPECTION

Date of Assignment: 24/10/2024

Liu's Brother Auto Engineering Workshop (kaki

Bukit) (HQ)

24/10/2024 Inspected At: Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Date Inspected:

Singapore 417883, Kaki Bukit

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA Daphne Lee Mooi Ngiuk Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Dec 2024)

Parts: TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE7525G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented / Bent	2,159.30 F	*2,159.30 FL
2	1		*REAR TAILGATE INNER LOCK	Serviceable	399.20 F	*- FL
3	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	388.50 F	*- FL
4	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
5	1		*REAR TAILGATE 8 PAX STICKER	Necessary	15.00 FS	*10.00 FS
6	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
7	1		*REAR BUMPER	Dented / Deformed	681.40 F	*681.40 FL
8	1		*SET REAR BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
9	1		*REAR BUMPER REVERSE SENSOR	Serviceable	220.00 FS	*- FS
10	1		*REAR END PANEL OUTER	Dented	665.20 F	*665.20 FL
11	1		*REAR END PANEL INNER	Repair	795.40 F	*- FL
12	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
13	1		*REAR CORPORATE ADVERTISEMENT & ARTWORK	Necessary	400.00 FS	*150.00 FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	5,894.00	3,745.90
	- List Item Discount on L Items 0.00/25.00% (S\$)				0.00	876.48
				Total Parts (S\$)	5,894.00	2,869.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	80.00	30.00		
2	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	120.00	100.00		
3	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	100.00	60.00		
4	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	600.00		
5	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	800.00	500.00		
6	TO APPLY RUST PROOFING RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	100.00	50.00		
	Gross Labour	Cost (S\$)	2,000.00	1,340.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >