

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580

Our File No: CS/III24100422/UNP3M4**Date:** 22/11/2024REFERENCE

Insured/Claimant: NG SHAO WEI Policy No: D24MPC0003636
Date of Loss: 21/10/2024 Nature of Claim: OD Claim No: MPC2024D0012470

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ4541X**
Make & Model: HYUNDAI HD AVANTE, 1.6 (A) Engine No: G4FC9U653212
Reg. Date: 13/05/2009 (Man. Year: 2009) Chassis No: KMH DU41BR9U758042
Colour: Black Odometer: 172517 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$35,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17
Front Left Side: Triangle 5 mm Rear Left Side: Triangle 5 mm
Front Right Side: Triangle 5 mm Rear Right Side: Triangle 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,187.84	9,186.08	3,001.76	24.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,550.00	1,980.00	2,570.00	56.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,737.84	11,166.08	5,571.76	33.29
Approved Total (Overridden) (S\$)		8,900.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	16,137.84	8,300.00	7,837.84	48.57
+ GST 9.00/9.00% (S\$)	1,452.41	747.00	705.41	48.57
Nett Amount (S\$)	17,590.25	9,047.00	8,543.25	48.57

INSPECTION

Date of Assignment: 24/10/2024

Date Inspected: 24/10/2024 Inspected At:

BLUWEL AUTOMOTIVE SERVICE PTE LTD (HQ)
BLK 1 KAKI BUKIT AVE 6
#01-28/53/55/56 (MAIN OFFICE)
SINGAPORE 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2024)
Parts:	143	HYUNDAI HD AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ4541X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	658.20 FL	*658.20 FL
2	1		*FRONT BUMPER TOP RUBBER SEAL	Not Necessary	85.20 FL	*- FL
3	2		*FRONT BUMPER TOP BRACKET	No such part	197.20 FL	*- FL
4	2		*FRONT BUMPER RETAINER	Bent	173.80 FL	*173.80 FL
5	1		*FRONT BUMPER SPONGE	Not fitted	225.60 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	589.50 FL	*319.20 FL
7	1		*FRONT BUMPER RADIATOR GRILLE	Cracked	1,082.90 FL	*582.00 FL
8	1		*SUPPORT PANEL TOP GARNISH	No such part	202.50 FL	*- FL
9	1		*FRONT SUPPORT PANEL	Cracked/Buckled	987.50 FL	*987.50 FL
10	2		*FRONT HEADLAMPS	Holder Cracked	3,512.80 FL	*1,962.00 FL
11	1		*FRONT BONNET	Buckled	1,971.20 FL	*1,971.20 FL
12	1		*FRONT BONNET INSULATOR	Deformed/Torn	385.90 FL	*241.20 FL
13	1		*RADIATOR	Bent/Punctured	619.00 FL	*619.00 FL
14	1		*RADIATOR FAN MOTOR ASSY	Cracked/Jammed	596.00 FL	*596.00 FL
15	1		*RADIATOR TOP HOSE	Twisted	42.00 FL	*42.00 FL
16	1		*RADIATOR BOTTOM HOSE	Not Necessary	42.00 FL	*- FL
17	1		*AIR CON CONDENSER	Bent	991.00 FL	*991.00 FL
18	1		*AIR CON SUCTION PIPE	Bent	643.00 FL	*302.00 FL
19	1		*AIR CON DISCHARGE PIPE	Serviceable	192.00 FL	*- FL
20	1		*NUMBER PLATE	Broken	30.00 FL	*30.00 FL
21	1		*BONNET LOCK	Bent/Twisted	97.00 FL	*97.00 FL
22	2		*BONNET HINGES	Bent	170.00 FL	*170.00 FL
23	1		*HORN UNIT	Cracked	98.50 FL	*98.50 FL
24	1		*INLET MANIFOLD	Cracked	1,085.00 FL	*1,085.00 FL
25	1		*FRONT WIRE HARNESS	Torn	435.00 FL	*435.00 FL
26	1		*FRONT FENDER INNERSHIELD	Torn	122.00 FL	*122.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	15,234.80	11,482.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,046.96	2,296.52
Total Parts (\$\$)	12,187.84	9,186.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	200.00	60.00
2	REMOVE & REFIX FRONT UNDERCARRIAGE	New	400.00	0.00
3	REMOVE & REFIX FRONT PORTION, KNOCKING, WELDING, CUT & JACK	New	1,800.00	900.00
4	CHASSIS FRAME. ALIGNMENT (NPA)	New	0.00	0.00
5	RESPRAY FRONT PORTION. TOUCH-UP & POLISHING	New	1,500.00	900.00
6	ELECTRICAL & FOCUS WIRING	New	50.00	20.00
7	COMPUTERIZE & 4 WHEELS ALIGNMENT	New	100.00	0.00
8	TO REMOVE & REFIX FRONT SUPPORT PANEL & HEADLAMP RH. ALIGNMENT	New	400.00	0.00
9	REMOVE AIR CON & REFILL GAS	New	100.00	100.00
Gross Labour Cost (S\$)			4,550.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >