



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 ATTN: IRENE TAY			Ref: CS/CTI24100424/Enh3e2(N) Date: 28/03/2025 Code: CTI	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	<b>Insured Veh.</b>		<b>Veh. Inspected</b>	GBL 822H
	<b>Policy No.</b>	DMCVSNA00027282400	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	SNM24D205904	<b>Excess (\$)</b>	4,000.00
	<b>Assign From</b>	IRENE TAY	<b>Assign Date</b>	24/10/2024
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA HIACE	<b>c.c</b>	2754
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2021
	<b>Chassis No.</b>	GDH2012015855	<b>Colour</b>	BLUE
	<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	195 R15C	TRIANGLE	5 mm
	<b>L/H Front Tyre</b>	195 R15C	TRIANGLE	5 mm
	<b>R/H Rear Tyre</b>	195 R15C	TRIANGLE	5 mm
	<b>L/H Rear Tyre</b>	195 R15C	TRIANGLE	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	13/10/2024	<b>Inspection Date</b>	24/10/2024
	<b>Survey held at</b>	DING AUTO PTE LTD 60 JLN LAM HUAT CARROS CENTRE #06-46/47 SINGAPORE 737869		
<b>5a. Remarks</b>				
	A)THE MARKET VALUE IS S\$89,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>20 Working Days</b>	