

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI24100426/UNP3E2**Date:** 14/11/2024REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBG3391R**Insured Vehicle No :** YP8507Y

Date of Loss: 19/10/2024

Nature of Claim: TP

Claim No: CDMFG24002709

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBG3391R**

Make & Model: TOYOTA HIACE, 3.0 D (M)

Engine No: 1KD2693909

Reg. Date: 20/07/2017 (Man. Year: 2017)

Chassis No: KDH2015026726

Colour: White

Odometer: 287994 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

195 R15

Front Left Side: Agilis 6 mm

Rear Left Side:

Agilis 6 mm

Front Right Side: Agilis 6 mm

Rear Right Side:

Agilis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,395.89	3,110.71	7,285.18	70.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	1,100.00	3,260.00	74.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,755.89	4,210.71	10,545.18	71.46
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	14,755.89	3,300.00	11,455.89	77.64

INSPECTION

Date of Assignment: 24/10/2024

Date Inspected: 30/10/2024 Inspected At:

Tick Hai Motor & Welding Services - Kaki Bukit (HQ)
BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI
BUKIT
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Nov 2024)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG3391R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented / Bent	2,377.00 FL	*2,159.10 FL
2	1		*REAR BOOT TOYOTA LOGO	Necessary	76.10 FL	*76.10 FL
3	2		*REAR BOOT ABSORBER	Not Necessary	952.14 FL	*- FL
4	1		*REAR BOOT REAR VIEW MIRROR	Broken	334.60 FL	*280.10 FL
5	1		*REAR BOOT LOCK	Damaged / Jammed	393.63 FL	*393.63 FL
6	1		*REAR BOOT LOCK PROTECTOR	Serviceable	89.70 FL	*- FL
7	1		*REAR BOOT CATCH	Not Necessary	127.40 FL	*- FL
8	2		*REAR BOOT STOPPER	Not Necessary	219.65 FL	*- FL
9	2		*REAR BOOT STOPPER CUSHION	Not Necessary	97.61 FL	*- FL
10	1		*REAR NUMBER PLATE TOP GARNISH	Cracked	302.68 FL	*302.68 FL
11	2		*REAR NUMBER PLATE LAMP	Not Necessary	325.58 FL	*- FL
12	1		*REAR BOOT WEATHERSTRIP	Not Necessary	564.28 FL	*- FL
13	1		*SET REAR BOOT INNER TRIMBOARD CLIP	Not Necessary	50.00 FL	*- FL
14	2		*TAILLAMP	Cracked	947.89 FL	*776.00 FL
15	2		*SET TAILLAMP CLIP	Not Necessary	80.00 FL	*- FL
16	1		*REAR BUMPER	Repair	910.80 FL	*- FL
17	2		*REAR BUMPER SIDE RETAINER	Not Necessary	81.40 FL	*- FL
18	4		*REAR BUMPER CENTER BRACKET	Not Necessary	158.40 FL	*- FL
19	1		*SET REAR BUMPER CLIP	Not Necessary	50.00 FL	*- FL
20	2		*REAR CORNER GARNISH	Not Necessary	189.40 FL	*- FL
21	1		*END PANEL (INNER)	Not Necessary	804.10 FL	*- FL
22	1		*END PANEL (OUTER)	Repair	270.20 FL	*- FL
23	1		*REAR STEP PANEL	Not Necessary	266.40 FL	*- FL
24	1		*END PANEL TOP SCUFF PLATE	Not Necessary	219.40 FL	*- FL
25	1		*REAR FENDER (LH)	Repair	2,359.50 FL	*- FL
26	2		*REVERSE SENSOR	Serviceable	280.00 FS	*- FS
27	1		*HIACE STICKER	Necessary	30.00 FS	*30.00 FS
28	1		*8 PAX STICKER	Necessary	30.00 FS	*10.00 FS
29	1		*1200KG STICKER	Necessary	30.00 FS	*30.00 FS
30	1		*70KM/H STICKER	Necessary	30.00 FS	*10.00 FS
31	1		*LALAMOVE STICKER (KIV)	Necessary	120.00 FS	*- FS
32	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
33	1		*END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*REAR NUMBER PLATE GARNISH CHROME	Serviceable	180.00 FS	*- FS
35	1		*REAR VIEW CAMERA	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,457.86	4,107.61
- List Item Discount on L Items 25.00/25.00% (S\$)	3,061.97	996.90
Total Parts (S\$)	10,395.89	3,110.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR WIRING SYSTEM	New	80.00	20.00
2	TO REMOVE & INSTALL REVERSE SENSORS	New	120.00	0.00
3	TO REMOVE & INSTALL REAR INTERIOR GARNISHES, AND TRIMS TO FACILITATE	New	280.00	0.00
4	TO REOVE & REINSTALL REAR WINDSCREEN	New	150.00	100.00
5	TO TRANSFER REAR BOOT COMPONENTS FROM OLD BOOT TO NEW BOOT	New	150.00	50.00
6	TO APPLY ANTI-RUSTING COATING ON PANELS	New	280.00	30.00
7	LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING	New	1,500.00	400.00
8	TO PUTTY AND RESPRAY AFFECTED AREAS	New	1,800.00	500.00
Gross Labour Cost (S\$)			4,360.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >