



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS GREAT AMERICAN INSURANCE COMPANY	Ref:	CS/GAI24100427/Uqp3e2
3 TEMASEK AVENUE	Date:	04/11/2024
#16-01 CENTENNIAL TOWER	Code:	GAI
SINGAPORE 039190		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 5535U	Veh. Inspected	CB 8076H
Policy No.	MOMVC000008831-03-000	Coverage	0
Claim No.	CLMOMVC000004557	Excess	\$0.00
Assign From	JASMINE	Assign Date	24/10/2024

### 2. Vehicle Details

Make & Model	TOYOTA HIACE COMMUTER (M)	C.C	2982
Engine No.	1KD1911623	Year of Reg.	25/03/2009
Chassis No.	JTFJT02P600001263	Colour	WHITE
Odometer	545061 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	MICHELIN	7
L/H Front Tyre	195R15	MICHELIN	7
R/H Rear Tyre	195R15	AGILIS	7
L/H Rear Tyre	195R15	AGILIS	7

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	22/10/2024	Inspection Date	24/10/2024
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days