

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24100429/RVP3E2
Date: 27/01/2025REFERENCE

Insured/Claimant:	SIA BEE LENG (XIE MEILING)	Policy No:	1700075557
Date of Loss:	24/10/2024	Nature of Claim:	OD Claim No: 7101851406SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT9600L		
Make & Model:	AUDI Q2, 1.4 (A)	Engine No:	CHZ552573
Reg. Date:	14/11/2017 (Man. Year: 2017)	Chassis No:	WAUZZZGA8JA022854
Colour:	Grey	Odometer:	68422 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$52,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,860.68	8,349.60	5,511.08	39.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,452.00	3,102.00	2,350.00	43.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,312.68	11,451.60	7,861.08	40.70
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	18,912.68	11,051.60	7,861.08	41.57
+ GST 9.00/9.00% (\$\$)	1,702.14	994.64	707.50	41.57
Nett Amount (\$\$)	20,614.82	12,046.24	8,568.58	41.57

INSPECTION

Date of Assignment:	24/10/2024	
Date Inspected:	25/10/2024	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,253.00 FS	*1,002.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	387.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	247.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cracked	212.00 FS	*169.60 FS
5	1		*FRONT BUMPER AIR GUIDE GRILLE END CAP - RH	Scratched	74.00 FS	*59.04 FS
6	1		*FRONT BUMPER SPOILER	Deformed	374.00 FS	*298.80 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Serviceable	195.00 FS	*- FS
8	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	86.00 FS	*- FS
9	1		*FRONT BUMPER ADAPTOR - RH	Cracked	54.00 FS	*42.56 FS
10	1		*FRONT BUMPER GUIDE SECTION - RH	Cracked	45.00 FS	*35.92 FS
11	1		*LED HEADLIGHT - RH	Broken	5,892.00 FS	*4,713.60 FS
12	1		*LED HEADLIGHT POWER MODULE - RH	Serviceable	1,904.00 FS	*- FS
13	1		*LED HEADLIGHT SPACER - RH	Necessary	57.00 FS	*44.88 FS
14	1		*LIFT CYLINDER - RH	Serviceable	170.00 FS	*- FS
15	1		*LIFT CYLINDER HOSE	Serviceable	233.00 FS	*- FS
16	1		*LED HEADLIGHT MOUNTING - RH	Cracked	147.00 FS	*117.60 FS
17	1		*FRONT FENDER - RH	Bent	1,365.00 FS	*1,092.00 FS
18	1		*FRONT FENDER ATTACHMENT PARTS - RH	Not Necessary	47.00 FS	*- FS
19	1		*FRONT FENDER BRACKET - RH	Serviceable	20.00 FS	*- FS
20	1		*FRONT FENDER BRACKET - RH	Serviceable	62.00 FS	*- FS
21	1		*FRONT FENDER BRACKET - RH	Serviceable	20.00 FS	*- FS
22	1		*FRONT FENDER RIVET - RH (6PCS)	Necessary	26.00 FS	*20.16 FS
23	1		*FRONT FENDER BRACE - RH	Bent	67.00 FS	*52.88 FS
24	1		*FRONT WHEEL HOUSING LINER - RH	Serviceable	47.00 FS	*- FS
25	1		*LED HEADLIGHT BRACKET - RH	Bent	57.00 FS	*44.08 FS
26	2		*FRONT WHEEL ARCH COVER - LH / RH	Scratched / Necessary	804.00 FS	*640.80 FS
27	1		*SUNDRY	Necessary	15.68 FS	*15.68 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 13,860.68 8,349.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,200.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$)			5,452.00	3,102.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >