

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24100432/RQP3E2  
**Date:** 28/10/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
<b>Claimant Vehicle No :</b>	SBS3164S	<b>Insured Vehicle No :</b>	SJS9399Y
Date of Loss:	16/10/2024	Nature of Claim:	TP
		Claim No:	DMPC2401438H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBS3164S</b>	Engine No:	D99142039
Make & Model:	VOLVO B9TL, 9.4 D (A)	Chassis No:	YV3S4P926CA156599
Reg. Date:	09/07/2012 (Man. Year: 2012)	Odometer:	714688 km
Colour:	Multi-colour		
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,115.25	2,115.25	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	888.00	888.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,003.25</b>	<b>3,003.25</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 9.00/9.00% (S\$)</b>	270.29	270.29	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>3,273.54</b>	<b>3,273.54</b>	<b>0.00</b>	<b>0.00</b>

INSPECTION

Date of Assignment:	24/10/2024	
Date Inspected:	24/10/2024	Inspected At: Sbs Transit Pte Ltd (ulu Pandan) (HQ) Ulu Pandan WS, 1 Business Park Drive, Singapore 608506
Estimated Period of Repair:	1.0 days	

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Oct 2024)	
Parts:	N/A	VOLVO B9TL 9.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS3164S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR. LOWER BOOT	Bent	1,650.84 F	*1,650.84 F
2	1		*NUMBER PLATE RECESS PAN;EXT.RR	Cracked	168.61 F	*168.61 F
3	1		*PANEL. REAR BUMPER. O/S	Bent	191.40 F	*191.40 F
4	1		*REAR REVERSE LAMP;B9TL EU5	Cracked	83.00 F	*83.00 F
5	1		*LED LICENSE PLATE LAMP	Cracked	21.40 F	*21.40 F
F=Franchise part.						
Total Parts (S\$)					2,115.25	2,115.25

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE / REPLACE / REPAIR DAMAGED PARTS BY WORKSHOP	New	188.00	188.00
2	TO REMOVE / REPLACE / REPAIR DAMAGED PARTS BY CONTRACTOR	New	700.00	700.00
3	TO REMOVE / REPLACE / REPAIR DAMAGED ADVERTISEMENT PANEL (NPA)	New	0.00	0.00
4	TOWING COST (NPA)	New	0.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>888.00</b>	<b>888.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >