



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SGP 9061Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	BROKEN	\$600.00	\$600.00
2	FRONT FENDER L-R @\$500.00	N/S DENTED	\$1,000.00	\$500.00
2	FRONT HEADLAMP L-R @\$800.00	BROKEN	\$1,600.00	\$1,600.00
1	FRONT BUMPER REINFORCEMENT	DENTED	\$450.00	\$450.00
1	BONNET	DENTED	\$750.00	\$750.00
2	BONNET HINGE @\$60.00	BENT	\$120.00	\$120.00
1	SUPPORT PANEL	DENTED	\$550.00	\$550.00
1	FRONT WINDSCREEN	BROKEN	\$600.00	\$600.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	\$150.00	\$150.00
1	RADIATOR	BENT/TWISTED	\$650.00	\$650.00
2	RADIATOR FAN ASSY @\$400.00	BROKEN	\$800.00	\$800.00
1	AIRCON CONDENSER	BENT/TWISTED	\$450.00	\$450.00
1	AIRCON COMPRESSOR	* CHECK	\$650.00	\$0.00
2	AIRCON PIPE @\$300.00	* CHECK	\$600.00	\$0.00
1	ENGINE MANIFOLD	* CHECK	\$750.00	\$0.00
1	ALTERNATOR	* CHECK	\$550.00	\$0.00
1	ABS PUMP	* CHECK	\$1,800.00	\$0.00
1	ENGINE CHASSIS FRAME	TO REPAIR SEE LABOUR	\$700.00	\$0.00
1	WHEEL HUB PANEL L/H	TO REPAIR SEE LABOUR	\$500.00	\$0.00
1	ENGINE CROSSMEMBER	* CHECK	\$1,100.00	\$0.00
1	SET ENGINE MOUNTING	* CHECK	\$600.00	\$0.00
1	HYBRID BATTERY (RECON)	SHORTED/CHIPPED	\$4,000.00	\$4,000.00
1	DRIVER AIRBAG	BROKEN	\$1,800.00	\$1,800.00
1	FRONT PASSENGER AIRBAG	BROKEN	\$1,900.00	\$1,900.00
2	FRONT SIDE AIRBAG L-R @\$1350.00	BROKEN (1PC ONLY)	\$2,700.00	\$1,350.00
2	REAR SIDE AIRBAG L-R @\$1100.00	BROKEN (1PC ONLY)	\$2,200.00	\$1,100.00
1	ROOFLINING	CRUSHED	\$45.00	\$45.00
1	AIRBAG ECU	NECESSARY	\$1,500.00	\$1,500.00
2	FRONT SEAT BELT (LH&RH) @\$850.00	JAMMED	\$1,700.00	\$1,700.00
1	FRONT DOOR L/H	DENTED	\$650.00	\$650.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR GLASS L/H	BROKEN	\$450.00	\$450.00
1	FRONT SIDE MIRROR L/H	NOT NECESSARY	\$500.00	\$0.00
2	FRONT AND REAR DOOR PILLAR L/H	DENTED	\$1,700.00	\$1,700.00
	LESS 0.00 / 25.00% DISCOUNT		\$0.00	(\$5,853.75)
			\$34,115.00	\$17,561.25

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TOWING CHARGES		\$150.00	\$100.00
	TO REMOVE & REFIX REAR UNDERCARRIAGE		\$1,000.00	\$200.00
	TO RESPRAY UNDERCOATING		\$400.00	\$50.00
	PANEL BEATING, STRAIGHTEN CHASSIS REMOVE AND REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF ENGINE CHASSIS FRAME AND WHEEL HUB PANEL L/H		\$3,000.00	\$1,800.00
	TO REMOVE & REFIX WINDSCREEN		\$200.00	\$120.00
	TO CHECK, REMOVE, FIX ELECTRICAL WIRING		\$300.00	\$100.00
	REMOVE & REFIX AIRBAGS		\$1,000.00	\$300.00
	REMOVE & REFIX ROOFLINING		\$200.00	\$80.00
	TO RESPRAY PAINTING INCLUDING POLISH & WAXING ON DAMAGED PARTS		\$1,700.00	\$1,400.00
			\$7,950.00	\$4,150.00

GRAND TOTAL			\$42,065.00	\$21,711.25
--------------------	--	--	--------------------	--------------------

RECOMMENDED COST OF REPAIRS (EXCLUDE CHECK ITEMS S\$4,537.50 NETT)				\$21,711.25
---	--	--	--	--------------------

Report Ref No: CS/TP24100433/Enh3e2

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.