

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100437/APA3Q2
Date: 17/01/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210090728
Claimant Vehicle No :	PC7522J	Insured Vehicle No :	SCU2727C
Date of Loss:	18/10/2024	Nature of Claim:	TP
		Claim No:	3846364627SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC7522J	Engine No:	1GD8341293
Make & Model:	TOYOTA HIACE, 2.8 D COMMUTER GL (A)	Chassis No:	GDH2232000987
Reg. Date:	29/11/2018 (Man. Year: 2018)	Odometer:	517167 km
Colour:	White		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,985.75	4,355.67	6,630.08	60.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,220.00	1,610.00	3,610.00	69.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,205.75	5,965.67	10,240.08	63.19
Approved Total (Overridden) (S\$)		4,750.00		
(S\$)	16,205.75	4,750.00	11,455.75	70.69
+ GST 9.00/9.00% (S\$)	1,458.52	427.50	1,031.02	70.69
Nett Amount (S\$)	17,664.27	5,177.50	12,486.77	70.69
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		5,904.75		

INSPECTION

Date of Assignment:	22/10/2024	
Date Inspected:	22/10/2024	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	479.00 FL	*479.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	110.00 FL	*- FL
3	4		*REAR BUMPER BRACKET	Not Necessary	84.80 FL	*- FL
4	1		*TAIL LAMP RH	Cracked	390.00 FL	*390.00 FL
5	1		*TAIL LAMP LOWER GARNISH RH	Torn	167.00 FL	*167.00 FL
6	1		*TAIL LAMP LOWER GARNISH RETAINER RH	Not Necessary	65.00 FL	*- FL
7	1		*TAILGATE	Dented	2,054.30 FL	*2,054.30 FL
8	1		*TAILGATE LOGO	Necessary	75.20 FL	*75.20 FL
9	1		*TAILGATE CENTER MOULDING (CHROME)	Not Necessary	674.80 FL	*- FL
10	1		*TAILGATE EMBLEM HIACE	Necessary	57.40 FL	*57.40 FL
11	1		*TAILGATE EMBLEM GL	Necessary	58.40 FL	*58.40 FL
12	1		*TAILGATE STOPPER	Not Necessary	28.00 FL	*- FL
13	1		*TAILGATE WEATHERSTRIP	Torn	395.00 FL	*395.00 FL
14	1		*TAILGATE WEATHERSTRIP PROTECTOR	Deformed	485.20 FL	*485.20 FL
15	1		*TAILGATE INNER LOCK	Damaged	475.60 FL	*385.00 FL
16	1		*TAILGATE LOWER LOCK	Not Necessary	45.20 FL	*- FL
17	2		*TAILGATE LOWER CORNER GARNISH	Not Necessary	39.20 FL	*- FL
18	1		*REAR END PANEL (OUTER)	Dented	597.00 FL	*597.00 FL
19	1		*REAR END PANEL (EXTEND) RH	Repair	362.10 FL	*- FL
20	1		*REAR FLOOR PANEL	Not Necessary	1,888.90 FL	*- FL
21	1		*REAR FLOOR PANEL MAT	Not Necessary	1,591.50 FL	*- FL
22	1		*REAR SIDE PANEL INNER TRIM RH	Cracked	257.40 FL	*257.40 FL
23	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
24	1		*SET TAIL LAMP CLIP	Not Necessary	60.00 FS	*- FS
25	1		*SET TAILLAMP LOWER GARNISH CLIP	Not Necessary	40.00 FS	*- FS
26	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
27	1		*SET TAILGATE CENTER MOULDING CLIP	Not Necessary	80.00 FS	*- FS
28	1		*SET TAILGATE LOWER CORNER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
29	1		*SET TAILGATE INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
30	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
31	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	70.00 FS	*70.00 FS
32	1		*TAILGATE STICKER 70KN/H	Necessary	30.00 FS	*15.00 FS
33	1		*TAILGATE STICKER EMERGENCY EXIT	Necessary	60.00 FS	*60.00 FS
34	1		*REAR END PANEL (OUTER) SEALANT	Necessary	150.00 FS	*60.00 FS
35	1		*REAR END PANEL (EXTEND) SEALANT	Not Necessary	150.00 FS	*- FS
36	1		*REAR FLOOR TOP BOARD	Not Necessary	1,800.00 FS	*- FS
37	1		*REAR FLOOR PANEL SEALANT	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,581.00	5,705.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,595.25	1,350.23
Total Parts (\$\$)	10,985.75	4,355.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND REPLACE PARTS	New	2,200.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	600.00
3	WIRING BULB CHECKING	New	180.00	30.00
4	TRANSFER TAILGATE MECHANISM	New	80.00	60.00
5	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
6	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
7	REMOVE AND REFIX VIDEO RECORDER	New	80.00	50.00
8	REMOVE AND REFIX REAR REVERSE CAMERA	New	80.00	50.00
9	REMOVE AND REFIX LINING & SEATS	New	480.00	0.00
10	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	New	100.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
			Gross Labour Cost (\$\$)	5,220.00
				1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >