

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III24100438/RVP3E2
Date: 07/11/2024REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SBS6719Y	Insured Vehicle No :	SLG1294H
Date of Loss:	13/10/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS6719Y	Engine No:	90292609015946
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 D (A)	Chassis No:	WEB62808323125324
Reg. Date:	13/02/2014 (Man. Year: 2013)	Odometer:	944554 km
Colour:	Multi-colour		
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	56.22	56.22	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	388.00	388.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	444.22	444.22	0.00	0.00
+ GST 9.00/9.00% (\$\$)	39.98	39.98	0.00	0.00
Nett Amount (\$\$)	484.20	484.20	0.00	0.00

INSPECTION

Date of Assignment:	24/10/2024	Sbs Transit Pte Ltd (ulu Pandan) (HQ)
Date Inspected:	24/10/2024 Inspected At:	Ulu Pandan WS, 1 Business Park Drive, Singapore 608506.
Estimated Period of Repair:	1.0 days	Singapore 608506

Adjuster: VERON CHEN**Manager:** MOHD RASUL*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Nov 2024)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS6719Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BLINKER LAMP; FRT LEFT	Cracked	56.22 F	*56.22 F
						F=Franchise part.
Total Parts (S\$)					56.22	56.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE / REPLACE / REPAIR DAMAGED PARTS BY WORKSHOP	New	188.00	188.00
2	TO REMOVE / REPLACE / REPAIR DAMAGED PARTS BY CONTRACTOR	New	200.00	200.00
3	TO REMOVE / REPLACE / REPAIR DAMAGED ADVERTISEMENT PANEL (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			388.00	388.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >