

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24100440/KQP3E2
Date: 26/11/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003678212
Claimant Vehicle No :	SKJ8887Y	Insured Vehicle No :	FBL1351T
Date of Loss:	22/10/2024	Nature of Claim:	TP
		Claim No:	377874

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ8887Y		
Make & Model:	BMW 216D, 1.5 D GRAN TOURER LED NAV 7 SEATER (A)	Engine No:	32069420B37C15A
Reg. Date:	29/01/2016 (Man. Year: 2015)	Chassis No:	WBA2E32060P837011
Colour:	Metallic Blue	Odometer:	157814 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,046.60	5,027.91	2,018.69	28.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,270.00	760.00	37.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,076.60	6,297.91	2,778.69	30.61
Approved Total (Overridden) (\$\$)		5,000.00		
(\$\$)	9,076.60	5,000.00	4,076.60	44.91
+ GST 9.00/9.00% (\$\$)	816.89	450.00	366.89	44.91
Nett Amount (\$\$)	9,893.49	5,450.00	4,443.49	44.91

INSPECTION

Date of Assignment:	25/10/2024		
Date Inspected:	01/11/2024	Inspected At:	Thiam Heng Huat Pte Ltd (SIN MING) 176 SIN MING DRIVE, #05-14 Singapore 575721
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2024)
Parts:	M1-MPV	BMW 216D 1.5 D GRAN TOURER LED NAV 7 SEATER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ8887Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,690.00 F	*1,690.00 FL
2	1		*REAR TAILGATE EMBLEM	Necessary	128.00 F	*128.00 FL
3	1		*REAR TAILGATE REFLECTOR LH	Cut	339.20 F	*339.20 FL
4	1		*REAR TAILGATE LOCK	Repair	343.00 F	*. FL
5	1		*REAR TAILGATE RUBBER	Serviceable	195.80 F	*. FL
6	1		*REAR BUMPER	Buckled	1,288.30 F	*1,288.30 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	632.30 F	*632.30 FL
8	1		*REAR BUMPER INNER BRACKET LH	Cracked	132.00 F	*132.00 FL
9	1		*REAR BUMPER REFLECTOR LH	Cracked	90.00 F	*90.00 FL
10	1		*TAILLAMP LH	Cut	598.00 F	*598.00 FL
11	1		*REAR END PANEL	Repair	1,135.00 F	*. FL
12	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
13	1		*REAR NO. PLATE	Serviceable	60.00 FS	*. FS
14	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
15	1		*REAR BUMPER REVERSE SENSOR	Cut / Shorted	285.00 FS	*285.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,046.60	5,272.80
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	244.89
Total Parts (\$\$)	7,046.60	5,027.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT DAMAGED PARTS, CUT / WELD DAMAGED AREAS	New	800.00	500.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	800.00	550.00
3	TO REMOVE AND REFIT REAR WINDSCREEN	New	200.00	120.00
4	TO REMOVE AND REFIT REVERSE SENSOR	New	100.00	50.00
5	CHECK WIRING	New	50.00	20.00
6	TUFF COATING	New	80.00	30.00
Gross Labour Cost (\$\$)			2,030.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >