

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CTI24100444/UVH3E2
Date: 12/11/2024REFERENCEInsured/Claimant: AUTOBAHN RENT A CAR PTE. LTD. Policy No: DMHCSNA00004652400
Date of Loss: 16/10/2024 Nature of Claim: OD Claim No: SNM24D205964/C01/LEEPGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNS7599C**
Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No: G4LEPU381676
Reg. Date: 29/08/2024 (Man. Year: 2024) Chassis No: KMHLN41JVRU120816
Colour: Grey Odometer: 0 km
Engine Capacity: 1580 cc
Market Value/New Car Price: S\$164,000.00
Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:CONDITION OF TYRESFront Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Kumho 8 mm Rear Left Side: Kumho 8 mm
Front Right Side: Kumho 8 mm Rear Right Side: Kumho 8 mm*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 0.00 | 0.00 | 0.00 | |
| - Excess (S\$) | 2,000.00 | 2,000.00 | 0.00 | 0.00 |
| Nett Amount (S\$) | -2,000.00 | -2,000.00 | 0.00 | 0.00 |

INSPECTIONDate of Assignment: 25/10/2024
Date Inspected: 25/10/2024 Inspected At: Ky Auto Pte Ltd (HQ)
25 KAKI BUKIT ROAD 4 SYNERGY@KB #05-23
Singapore 417800
Estimated Period of Repair: 0.0 days**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

| | |
|----------------------------|--------------|
| Market Value : | \$164,000.00 |
| OMV : | \$25,807.00 |
| PARF Rebate (1) : | \$17,347.00 |
| Quota Premium Paid : | \$93,900.00 |
| COE Rebate (2) : | \$92,410.00 |
| Total Rebate (1) + (2) = : | \$109,757.00 |

The total amount incurred will be Market Value \$164,000.00 minus Total Rebate \$109,757.00 \$ = \$54,243.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 12 Nov 2024) |
| Parts: | 143 | HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SNS7599C) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >