

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Oct 2024)

Parts: 213 TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: CYS Automobile Services Pte Ltd/GBD409K/24/10/2024 14:51

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	bt- *410.00 F
2	2		*BONNET HINGES	0.00	0.00	bt- *66.00 F
3	1		*BONNET LOCK	0.00	0.00	bt- *59.00 F
4	1		*BONNET EMBLEM	0.00	0.00	cu- *35.00 F
5	1		*FRONT GRILLE	0.00	0.00	mis- *235.00 F
6	2		*FRONT CORNER PANEL	0.00	0.00	bt- *196.00 F
7	2		*HEADLAMP ASSY	0.00	0.00	an- *660.00 F
8	1		*FRONT BUMPER	0.00	0.00	mis- *250.00 F
9	1		*FRONT BUMPER BEAM	0.00	0.00	bt- *100.00 F
10	2		*FRONT BUMPER BRACKETS	0.00	0.00	dis- *190.00 F
11	2		*FRONT BUMPER SIDE RETAINERS	0.00	0.00	de- *150.00 F
12	2		*FRONT BUMPER STAY	0.00	0.00	Xun- *116.00 F
13	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	bb- *170.00 F
14	2		*FRONT BUMPER REINFORCEMENT STAY	0.00	0.00	bt- *116.00 F
15	1		*FRONT BUMPER TOWING COVER	0.00	0.00	mis- *15.00 F
16	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	mis- *80.00 F
17	2		*FRONT BUMPER FOG LAMP COVER	0.00	0.00	mis- *70.00 F
18	1		*FRONT SUPPORT PANEL	0.00	0.00	bt- *185.00 F
19	1		*FRONT SUPPORT PANEL TOP GARNISH	0.00	0.00	cut- *140.00 F
20	1		*FRONT BRACE PANEL	0.00	0.00	bt- *35.00 F
21	1		*WASHER TANK	0.00	0.00	de- *85.00 F
22	1		*TURBO COOLER <i>disassemble photo</i>	0.00	0.00	dd- *700.00 F
23	1		*AIR-CON CONDENSER <i>disassemble</i>	0.00	0.00	bt- *690.00 F
24	1		*AIR-CON CONDENSER FAN COWLING	0.00	0.00	ora- *170.00 F
25	1		*AIR-CON CONDENSER FAN BLADE	0.00	0.00	Xun- *90.00 F
26	1		*AIR-CON CONDENSER FAN MOTOR	0.00	0.00	Xun- *590.00 F
27	1		*AIR-CON ALUMINIUM PIPE	0.00	0.00	bt- *390.00 F
28	1		*AIR-CON SUCTION PIPE	0.00	0.00	bt- *370.00 F
29	1		*AIR-CON DISCHARGE HOSE	0.00	0.00	bt- *380.00 F
30	1		*RADIATOR	0.00	0.00	bt- *780.00 F
31	1		*RADIATOR FAN COWLING	0.00	0.00	Xun- *160.00 F
32	1		*RADIATOR FAN BLADE	0.00	0.00	Xun- *85.00 F
33	1		*RADIATOR FAN MOTOR	0.00	0.00	Xun- *580.00 F
34	1		*RADIATOR SPARE TANK	0.00	0.00	cu- *160.00 F
35	1		*AIR CLEANER ASSY	0.00	0.00	cu- *330.00 F
36	1		*AIR DUCT	0.00	0.00	cu- *85.00 F
37	1		*HORN	0.00	0.00	cu- *55.00 F
38	1		*AIR-CON BLOWER ASSY	0.00	0.00	wq- *670.00 F
39	1		*AIRE HARDNESS COVER RH	0.00	0.00	wq- *75.00 F
40	1		*FRONT DOOR RH	0.00	0.00	bt- *750.00 F
41	1		*FRONT DOOR PILLAR RH	0.00	0.00	bt- *290.00 F
42	1		*FRONT DOOR STEP GARNISH RH	0.00	0.00	cut- *88.00 F

F=Franchise part.

Sub Total (\$\$) 9230 10,851.00

+ Margin on L,N Items 10.00% (\$\$) 10153 1,085.10

CYS Automobile Services Pte Ltd/GBD409K/24/10/2024 14:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						11,936.10

CYS Automobile Services Pte Ltd/GBD409K/24/10/2024 14:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

- | No | Qty | Particulars |
|----|-----|----------------------|
| 1 | 1 | DOOR COMPANY STICKER |
| 2 | 1 | FRONT NUMBER PLATE |

RM 30.00

MY 35.00

Sub Total (\$\$)

65.00

65

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

- | No | Particulars | Lab.Type | Amount |
|----|---|----------|----------|
| 1 | TO REMOVE AIR-CON CONDENSER, PIPE, DRIER AND TOP-UP AIR-CON GAS | New | 120.00 |
| 2 | TO DISMANTLE AND REFIX DASHBOARD | New | 300.00 |
| 3 | TO CHECK WIRING FUNCTION | New | 30.00 |
| 4 | TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL | New | 80.00 |
| 5 | LABOUR CHARGES FOR REMOVING, REFITTING AND REPAIRING OF AFFECTED ACCIDENT PARTS | New | 1,200.00 |
| 6 | TO PUTTY AND SPRAY PAINTING CHARGES | New | 900.00 |

Gross Labour Cost (\$\$) 2280 2,630.00

CYS Automobile Services Pte Ltd/GBD409K/24/10/2024 14:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park, Singapore 757700
Tel: 6219 2098 (3 lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 27445749/6256356 18 days
wp No Authorise
EX \$1000 28/10/24 2pm
4/5 Resurvey after repair
taufik@khauto.com
8 days

10153

65

2280

12498 45\$10K