

ASS. REC. BY: Taufik

REF: CS/11524100448/Top3

COE 2029/03

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: 91000
(Client's Record)
Make of Veh: _____


(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal or Market Value: \$45K
IDAC Accident Report _____ Consistent? : Yes or No
GIA / PR Seer: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / ☒ REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: G1BD409K Yr Regn: 2014, 64
Type: M.Car / M.Cycle / Bus / ☒ Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Hiace c.c. 2982
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 377 627 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: STFHT02P100133779
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: Inorder / ☒ Jammed / Leaked / Burnt or
Brake: Inorder / ☒ Jammed / Leaked / Burnt or
Modl: NV / S/Rim / STD A/Rim or
Tyre Size: F: 195/R15
R: 17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or LingLong
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 28/10/24
Survey held at CYSWL
Des. of Damages: ☒ Fr / Rear / O/S / N/S / U/G / Rooftop or

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair limit 913000</u>

Date/Time, File Pass to? ☐ : Prell. Report
1) ☐ : Final Report
Date/Time, File Return to?
2) _____
Days Of Repair: _____
Resurvey No. of Trip: _____
Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$)
Survey Fee: _____
Transportation: _____
\$ + RS. \$ _____
Photos: _____



進友成汽車服務私人有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 3970
Policy No:	MCV24B00017900	Date of Loss:	23/10/2024
Vehicle Reg. No.:	GBD409K	Driveable?	
Driver Age/Info:	70 / MALE / OTHERS: -	Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MING XIN TRADING (1997)	Contact No:	+6596646094
Driver:	KWA CHWEE HOE		

Make/Model:	TOYOTA HIACE, 3.0 D TURBO 5DR (M)	Vehicle Reg. Date:	28/04/2014
Vehicle Colour:	WHITE		
Engine No:	1KD2373137	Chassis No:	JTFHT02P100133779
Odometer:	377626 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		

Description of Accident/Loss: ON THE ABOVE-MENTIONED DATE & TIME, I WAS TRAVELLING ALONG BKE TO WOODLANDS. VEHICLE B IN FRONT OF ME BRAKE. I COULDN'T BRAKE IN TIME AND COLLIDED ONTO VEHICLE B REAR PORTION. WHEN I GET DOWN OF MY VEHICLE, I REALIZED IT WAS A 3 VEHICLE CHAIN COLLISION.

Present Location: CYS AUTOMOBILE SERVICES PTE LTD (WOODLANDS)

COST OF CLAIMS

	Amount
Parts	11,936.10
Miscellaneous Items	65.00
Labour	2,630.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	14,631.10
- Excess (S\$)	600.00
(S\$)	14,031.10
+ GST 9.00% (S\$)	1,262.80
Nett Amount (S\$)	15,293.90

This claim is handled by: TEE WEE SIN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Oct 2024)
 Parts: 213 TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: CYS Automobile Services Pte Ltd/GBD409K/24/10/2024 14:51
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	bt-410.00 F
2	2		*BONNET HINGES	0.00	0.00	bt-66.00 F
3	1		*BONNET LOCK	0.00	0.00	bt-59.00 F
4	1		*BONNET EMBLEM	0.00	0.00	ua-35.00 F
5	1		*FRONT GRILLE	0.00	0.00	mis-235.00 F
6	2		*FRONT CORNER PANEL	0.00	0.00	bt-196.00 F
7	2		*HEADLAMP ASSY	0.00	0.00	an-660.00 F
8	1		*FRONT BUMPER	0.00	0.00	mis-250.00 F
9	1		*FRONT BUMPER BEAM	0.00	0.00	bt-100.00 F
10	2		*FRONT BUMPER BRACKETS	0.00	0.00	de-190.00 F
11	2		*FRONT BUMPER SIDE RETAINERS	0.00	0.00	de-150.00 F
12	2		*FRONT BUMPER STAY	0.00	0.00	?-116.00 F
13	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	bb-170.00 F
14	2		*FRONT BUMPER REINFORCEMENT STAY	0.00	0.00	bt-116.00 F
15	1		*FRONT BUMPER TOWING COVER	0.00	0.00	mis-15.00 F
16	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	mis-80.00 F
17	2		*FRONT BUMPER FOG LAMP COVER	0.00	0.00	mis-70.00 F
18	1		*FRONT SUPPORT PANEL	0.00	0.00	bt-185.00 F
19	1		*FRONT SUPPORT PANEL TOP GARNISH	0.00	0.00	*140.00 F
20	1		*FRONT BRACE PANEL	0.00	0.00	bt-35.00 F
21	1		*WASHER TANK	0.00	0.00	de-85.00 F
22	1		*TURBO COOLER <i>disassemble photo</i>	0.00	0.00	dd-700.00 F
23	1		*AIR-CON CONDENSER <i>disassemble</i>	0.00	0.00	bt-690.00 F
24	1		*AIR-CON CONDENSER FAN COWLING	0.00	0.00	?-170.00 F
25	1		*AIR-CON CONDENSER FAN BLADE	0.00	0.00	?-90.00 F
26	1		*AIR-CON CONDENSER FAN MOTOR	0.00	0.00	?-590.00 F
27	1		*AIR-CON ALUMINIUM PIPE	0.00	0.00	?-390.00 F
28	1		*AIR-CON SUCTION PIPE	0.00	0.00	?-370.00 F
29	1		*AIR-CON DISCHARGE HOSE	0.00	0.00	?-380.00 F
30	1		*RADIATOR	0.00	0.00	bt-780.00 F
31	1		*RADIATOR FAN COWLING	0.00	0.00	?-160.00 F
32	1		*RADIATOR FAN BLADE	0.00	0.00	?-85.00 F
33	1		*RADIATOR FAN MOTOR	0.00	0.00	?-580.00 F
34	1		*RADIATOR SPARE TANK	0.00	0.00	an-160.00 F
35	1		*AIR CLEANER ASSY	0.00	0.00	an-330.00 F
36	1		*AIR DUCT	0.00	0.00	an-85.00 F
37	1		*HORN	0.00	0.00	an-55.00 F
38	1		*AIR-CON BLOWER ASSY	0.00	0.00	?-670.00 F
39	1		*AIRE HARDNESS COVER RH	0.00	0.00	?-75.00 F
40	1		*FRONT DOOR RH	0.00	0.00	bt-750.00 F
41	1		*FRONT DOOR PILLAR RH	0.00	0.00	*290.00 F
42	1		*FRONT DOOR STEP GARNISH RH	0.00	0.00	cut-88.00 F

F=Franchise part.

Sub Total (S\$)

10,851.00

+ Margin on L,N Items 10.00% (S\$)

1,085.10

CYS Automobile Services Pte Ltd/GBD409K/24/10/2024 14:51. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						11,936.10

CYS Automobile Services Pte Ltd/GBD409K/24/10/2024 14:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	DOOR COMPANY STICKER
2	1	FRONT NUMBER PLATE

RM 30.00

MY 35.00

Sub Total (S\$) 65.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO REMOVE AIR-CON CONDENSER, PIPE, DRIER AND TOP-UP AIR-CON GAS	New	100	120.00
2	TO DISMANTLE AND REFIX DASHBOARD	New	200?	300.00
3	TO CHECK WIRING FUNCTION	New	✓	30.00
4	TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL	New	50	80.00
5	LABOUR CHARGES FOR REMOVING, REFITTING AND REPAIRING OF AFFECTED ACCIDENT PARTS	New	900	1,200.00
6	TO PUTTY AND SPRAY PAINTING CHARGES	New	800	900.00

Gross Labour Cost (S\$) 2,630.00

CYS Automobile Services Pte Ltd/GBD409K/24/10/2024 14:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park, Singapore 757700
Tel: 6219 2098 (3 lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 27445749/62563561
WP No Authorise
EX \$1000 28/10/24 Egm
L/S Resurvey after repair
taufik@khauto.com
8 days