

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24100450/ENP3E2
Date: 05/11/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAB00505
Claimant Vehicle No :	SHA2042R	Insured Vehicle No :	SMM5420R
Date of Loss:	23/10/2024	Nature of Claim:	TP
		Claim No:	M2406246

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2042R	Engine No:	G4LEKU406579
Make & Model:	HYUNDAI IONIQ, 1.6 (A)	Chassis No:	KMHC851CVLU189287
Reg. Date:	27/02/2020 (Man. Year: 2019)	Odometer:	540375 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,980.08	1,101.12	878.96	44.39
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	780.00	680.00	100.00	12.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,772.08	1,793.12	978.96	35.31
Approved Total (Overridden) (\$\$)		1,450.00		
(\$\$)	2,772.08	1,450.00	1,322.08	47.69
+ GST 9.00/9.00% (\$\$)	249.49	130.50	118.99	47.69
Nett Amount (\$\$)	3,021.57	1,580.50	1,441.07	47.69

INSPECTION

Date of Assignment:	25/10/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	25/10/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Nov 2024)
Parts:	143	HYUNDAI IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA2042R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Broken	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Broken	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Not Necessary	138.10 FL	*- FL
6	1		*ANTENNA SMARTKEY	Not Necessary	40.50 FL	*- FL
7	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
8	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
9	1		*REAR NUMBER PLATE WITH TRIM COVER	Broken	55.00 F	*55.00 F
10	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	180.00 F	*- F
11	1		*RENEW ADVERTISEMENT STICKER	Necessary	300.00 F	*300.00 F
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	2,341.35 1,287.65
					- List Item Discount on L Items 20.00/20.00% (\$\$)	361.27 186.53
					Total Parts (\$\$)	1,980.08 1,101.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING CHARGE	New	300.00	280.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	20.00
Gross Labour Cost (\$)			780.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >