



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2507475

3 ANSON ROAD #16-00

INV Date 03/11/2025

SPRINGLEAF TOWER

Reference CD/CTI24100451/Rpa3q2

SINGAPORE 079909

Code CTI

ATTN: Jacqueline Tan

PROFESSIONAL SERVICE FEE

Vehicle No. SLC 1824A

Insured Veh. SNF 2699Z

Claim No. SNM24D206004

Policy No. DMHCSNA00020852400

Accident Date 23/10/2024

Inspection Date 25/10/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909 ATTN: Jacqueline Tan			Ref: CD/CTI24100451/Rpa3q2(N) Date: 03/11/2025 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNF 2699Z	Veh. Inspected	SLC 1824A
	Policy No.	DMHCSNA00020852400	Coverage (\$)	0.00
	Claim No.	SNM24D206004	Excess (\$)	0.00
	Assign From	JACQUELINE TAN	Assign Date	25/10/2024
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	RU11114361	Colour	BLACK
	Odometer	145576 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	DUNLOP	6 mm
	L/H Front Tyre	215/55 R17	DUNLOP	6 mm
	R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
	L/H Rear Tyre	215/55 R17	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S & FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/10/2024	Inspection Date	25/10/2024
	Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 1824A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT	BENT	1,100.90	1,100.90
1	REAR BOOT LOCK	CUT	178.20	178.20
1	REAR BOOT EMBLEM	NECESSARY	22.50	22.50
1	REAR BOOT WEATHERSTRIP	CUT	185.20	185.20
1	LH TAILLAMP	NOT NECESSARY	534.30	-
1	RH TAILLAMP	SERVICEABLE	2,070.60	-
1	FRONT BUMPER	DEFORMED	801.70	801.70
1	FRONT BUMPER TOW COVER	CUT	29.10	29.10
1	FRONT GRILLE	CRACKED	308.50	308.50
1	FRONT GRILLE EMBLEM	NECESSARY	27.80	27.80
1	FRONT BUMPER GRILLE	SERVICEABLE	86.70	-
1	REAR BUMPER	DEFORMED	532.10	532.10
2	REAR BUMPER RAD REFLECTOR @\$18.20	CRACKED	36.40	36.40
1	REAR END PANEL	BENT	461.90	461.90
1	RH FENDER OUTER GARNISH	NOT NECESSARY	150.20	-
2	FRONT BUMPER RETAINER @\$20.60	NECESSARY	41.20	41.20
1	FRONT BUMPER LOWER	SERVICEABLE	195.60	-
1	RH FOG LAMP	SCRATCHED	327.80	327.80
1	RH FOG LAMP GARNISH	SERVICEABLE	45.20	-
2	REAR BOOT LAMP @\$294.60	SERVICEABLE	589.20	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	263.20	-
1	REAR SPARE TYRE PANEL (ADDITIONAL)	BUCKLED	838.10	838.10
1	REAR SPARE TYRE SPONGE (ADDITIONAL)	DEFORMED	226.90	226.90
	LESS 20% DISCOUNT		-1,810.66	-1,023.66
			7,242.64	4,094.64
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE (SN) }	SCRATCHED	20.00	35.00
1	NUMBER PLATE GARNISH (SN) }	SCRATCHED	25.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
			85.00	75.00

Report Ref No. CD/CTI24100451/Rpa3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	LABOUR CHARGE. (ADDITIONAL)		500.00	500.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS .		120.00	120.00
	TO CHECK AND REWIRING.		50.00	30.00
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS.		800.00	700.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		1,200.00	800.00
			2,670.00	2,150.00
GRAND TOTAL			9,997.64	6,319.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,050.00

Report Ref No. CD/CTI24100451/Rpa3q2(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor


HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A




PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A




PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A




PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A




PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A



PHOTOGRAPHS FOR VEHICLE NO. : SLC 1824A

