

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24100454/UVP3E2
Date: 22/11/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002652672
Claimant Vehicle No :	SLP3469K	Insured Vehicle No :	SMJ3874T
Date of Loss:	23/10/2024	Nature of Claim:	TP
		Claim No:	377802

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP3469K	Engine No:	2NR8699690
Make & Model:	TOYOTA SIENTA, 1.5 X CVT (A)	Chassis No:	NSP1707064825
Reg. Date:	31/05/2017 (Man. Year: 2016)	Odometer:	104398 km
Colour:	Green		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,452.05	4,876.30	7,575.75	60.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	2,000.00	1,580.00	44.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,032.05	6,876.30	9,155.75	57.11
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	16,032.05	5,500.00	10,532.05	65.69
+ GST 9.00/9.00% (S\$)	1,442.88	495.00	947.88	65.69
Nett Amount (S\$)	17,474.93	5,995.00	11,479.93	65.69

INSPECTION

Date of Assignment:	25/10/2024	
Date Inspected:	25/10/2024	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2024)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP3469K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Serviceable	1,488.10 FL	*- FL
2	1		*REAR WINDSCREEN MOULDING	No such part	148.30 FL	*- FL
3	1		*TAILGATE	Dented / Bent	1,602.20 FL	*1,602.20 FL
4	1		*TAILGATE REAR LOGO	Necessary	68.50 FL	*68.50 FL
5	2		*TAILGATE REFLECTORS	Not Necessary	826.00 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Twisted	357.00 FL	*357.00 FL
7	1		*TAILGATE INNER LOCK	Damaged / Bent	489.80 FL	*489.80 FL
8	1		*TAILGATE LOCK STRIKER	Not Necessary	60.00 FL	*- FL
9	1		*REAR BUMPER	Deformed / Torn	622.30 FL	*501.70 FL
10	1		*REAR BUMPER CENTRE BLACK GARNISH	Distorted	386.70 FL	*288.50 FL
11	1		*REAR BUMPER REFLECTOR	Not Necessary	75.20 FL	*- FL
12	2		*REAR BUMPER SIDE BLACK GARNISHS	Grazed / Torn	391.00 FL	*391.00 FL
13	1		*REAR BUMPER LAMP CENTRE	Not Necessary	335.20 FL	*- FL
14	1		*REAR BUMPER SIDE RETAINER N/S	Not Necessary	130.00 FL	*- FL
15	1		*REAR END PANEL OUTER	Dented / Bent	699.10 FL	*699.10 FL
16	1		*REAR END PANEL INNER	Dented / Bent	559.10 FL	*559.10 FL
17	1		*REAR ANTENNA SENSOR	Cracked	350.00 FL	*199.80 FL
18	1		*REAR END PANEL TOP GARNISH	Twisted	268.90 FL	*268.90 FL
19	2		*TAILLAMPS	Not Necessary	1,301.00 FL	*- FL
20	2		*TAILLAMP HOUSING PANELS	Repair	1,300.60 FL	*- FL
21	1		*REAR FENDER INNER TRIM BOARD O/S	Serviceable	870.20 FL	*- FL
22	1		*REAR FLOOR PANEL	Repair	1,415.10 FL	*- FL
23	1		*REAR FLOOR PANEL TOP BOARD	Serviceable	622.30 FL	*- FL
24	1		*REAR FLOOR PANEL TOOLS TRAY	Warped / Cracked	422.80 FL	*422.80 FL
25	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
26	1		*SET REAR BUMPER REVERSE SENSOR	Malfunction	200.00 FS	*200.00 FS
27	1		*SET REAR BUMPER REFLECTOR	Scratched	80.00 FS	*60.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
29	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*20.00 FS
30	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
31	1		*SET TAILGATE INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*SET TAILGATE LIZARD STICKER DECAL (KIV)	Necessary	100.00 FS	*- FS
33	1		*SET TAILGATE STICKER DECAL (KIV)	Necessary	100.00 FS	*- FS
34	1		*SET TAILGATE OUTER PROTECTOR STRIP (KIV)	Twisted	80.00 FS	*- FS
35	1		*TAILGATE MUGEN EMBLEM	Necessary	60.00 FS	*50.00 FS
36	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	450.00 FS	*- FS
37	1		*REAR LICENCE PLATE	Cracked	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,149.40	6,338.40
- List Item Discount on L Items 25.00/25.00% (S\$)	3,697.35	1,462.10
Total Parts (S\$)	12,452.05	4,876.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	30.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	60.00
5	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	New	100.00	0.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
8	TO SPRAY PROOFING	New	180.00	60.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	750.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (\$\$)			3,580.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >