

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24100456/KVP3M4**Date:** 26/11/2024**REFERENCE**

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SLK1228D **Insured Vehicle No :** GBM6038K

Date of Loss: 22/10/2024 Nature of Claim: TP Claim No: DMCV2400227H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK1228D**

Make & Model: MERCEDES-BENZ GLB 180, 1.3 PROGRESSIVE (A) Engine No: 28291480857431

Reg. Date: 28/12/2022 (Man. Year: 2022) Chassis No: W1N2476842W262577

Colour: Metallic Pearl White Odometer: 28896 km

Engine Capacity: 1332 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55R18 Rear Tyre Size: 235/55R18

Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm

Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,618.80	5,050.33	16,568.47	76.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,490.00	1,170.00	2,320.00	66.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,108.80	6,220.33	18,888.47	75.23
Approved Total (Overridden) (S\$)		4,950.00		
(S\$)	25,108.80	4,950.00	20,158.80	80.29
+ GST 9.00/9.00% (S\$)	2,259.79	445.50	1,814.29	80.29
Nett Amount (S\$)	27,368.59	5,395.50	21,973.09	80.29

INSPECTION

Date of Assignment: 24/10/2024

Date Inspected: 05/11/2024 Inspected At: EM SOLUTION PTE LTD
160 SIN MING DRIVE
#03-19 SIN MING AUTOCITY
SINGAPORE 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2024)
Parts:	M1-SUV	MERCEDES-BENZ GLB 180 1.3 PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK1228D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	4,581.22 FL	*- FL
2	1		*TAILGATE GLASS	Serviceable	1,322.51 FL	*- FL
3	1		*TAILGATE M/B STAR	Necessary	86.95 FL	*86.95 FL
4	1		*TAILGATE EMBLEM GLB 180	Necessary	141.20 FL	*141.20 FL
5	1		*TAILGATE LAMPS - L/R	N/S Cut/ O/S Serviceable	1,162.86 FL	*581.43 FL
6	1		*TAILGATE INNER LOCK	Repair	755.13 FL	*- FL
7	1		*TAILGATE INNER LOCK COVER	Serviceable	192.96 FL	*- FL
8	1		*TAILGATE W/STRIP	Serviceable	322.71 FL	*- FL
9	2		*TAILGATE DAMPERS - L/R	Serviceable	1,622.90 FL	*- FL
10	2		*TAILGATE STOPPERS - L/R	Serviceable	84.40 FL	*- FL
11	1		*TAILLAMP - LH	Serviceable	894.35 FL	*- FL
12	1		*REAR BUMPER - TOP	Buckled	1,655.93 FL	*1,245.20 FL
13	1		*REAR BUMPER CHROME PLATE - TOP	Necessary	611.42 FL	*320.10 FL
14	1		*REAR BUMPER CTR PAD	Dented/Cracked	811.33 FL	*721.00 FL
15	1		*REAR BUMPER BOTTOM CHROME TRIM	Cracked	1,471.43 FL	*1,471.43 FL
16	1		*REAR BUMPER BOTTOM COVER - CTR	Serviceable	681.62 FL	*- FL
17	1		*REAR BUMPER REFLECTOR - LH	Cracked	112.10 FL	*112.10 FL
18	2		*REAR BUMPER PDC SENSORS - LH	Serviceable	562.66 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	1,055.90 FL	*680.00 FL
20	2		*REAR BUMPER SIDE BRACKETS - TOP	Serviceable	230.40 FL	*- FL
21	2		*REAR BUMPER LOWER BRACKETS	Serviceable	220.40 FL	*- FL
22	2		*REAR BUMPER SIDE RETAINERS - L/R	Serviceable	191.00 FL	*- FL
23	1		*REAR END PANEL	Repair	1,015.60 FL	*- FL
24	1		*REAR END PANEL TRIM	Serviceable	180.93 FL	*- FL
25	1		*REAR EXHAUST CHROME TRIM - LH	Dented	485.91 FL	*185.40 FL
26	1		*REAR EXHAUST INSULATOR	Serviceable	280.90 FL	*- FL
27	1		*REAR EXHAUST SILENCER	Repair	1,895.60 FL	*- FL
28	2		*REAR FENDER PROTECTORS - L/R	Serviceable	799.24 FL	*- FL
29	1		*REAR FOOT ACTIVATED SENSOR	Serviceable	391.33 FL	*- FL
30	1		*SET TAILGATE GLASS SEALANT	Not Necessary	120.00 FS	*- FS
31	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,000.89	5,604.81
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,382.09	554.48
Total Parts (\$\$)	21,618.80	5,050.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE, REFIX TAILGATE GLASS	New	180.00	0.00
3	TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	New	150.00	0.00
4	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	50.00
5	TO REMOVE, REFIX REAR EXHAUST SYSTEMS	New	120.00	0.00
6	TO RESPRAY UNDERCOATING	New	120.00	0.00
7	TO DIAGNOSE, ERASE FAULT MEMORY AFTER REPAIR	New	350.00	0.00
8	TO RESPRAY PAINTING AND ETC	New	1,200.00	600.00
9	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	1,200.00	500.00
Gross Labour Cost (\$\$)			3,490.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >