

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24100457/RVP3E2**Date:** 08/01/2025REFERENCE

Handling Insurer: ECICS Limited

Policy No:

**Claimant Vehicle No :**

SLW1199R

**Insured Vehicle No :**

SME4046L

Date of Loss: 23/10/2024

Nature of Claim:

TP

Claim No:

DMPC2401432H/AF

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLW1199R**

Make &amp; Model: BMW X3, 2.0 SDRIVE 20I ADAPTIVE HL LED FL (A)

Engine No: F497K356B48B20A

Reg. Date: 15/09/2020 (Man. Year: 2020)

Chassis No: WBATS720209C38862

Colour: Black

Odometer: 78859 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R19

Rear Tyre Size: 245/50 R19

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,279.00	5,907.30	1,371.70	18.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,960.00	5,795.00	2,165.00	27.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>15,239.00</b>	<b>11,702.30</b>	<b>3,536.70</b>	<b>23.21</b>
<b>+ GST 9.00/9.00% (\$\$)</b>	1,371.51	1,053.21	318.30	23.21
<b>Nett Amount (\$\$)</b>	<b>16,610.51</b>	<b>12,755.51</b>	<b>3,855.00</b>	<b>23.21</b>

INSPECTION

Date of Assignment: 24/10/2024

Date Inspected:

28/10/2024

Inspected At:

Eurokars Services Pte Ltd (Kung Chong)  
11 Kung Chong Road  
Singapore 159147

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2025)
<b>Parts:</b>	M1-SUV	BMW X3 2.0 SDRIVE 20I ADAPTIVE HL LED FL (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLW1199R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,598.75 F	*1,598.75 F
2	1		*LOWER BUMPER PANEL	Scratched	793.60 F	*793.60 F
3	1		*COVER, TOWING	Scratched	52.30 F	*52.30 F
4	1		*GUIDE FOR BUMPER RH	Cracked	143.85 F	*143.85 F
5	1		*GUIDE FOR BUMPER LH	Cracked	143.85 F	*143.85 F
6	1		*SIDE GUIDE, BUMPER LH	Serviceable	184.95 F	*- F
7	1		*SIDE GUIDE, BUMPER RH	Serviceable	184.95 F	*- F
8	1		*REINFORCEMENT COVER	Serviceable	123.85 F	*- F
9	1		*LOWER BUMPER UNDERRIDE GUARD	Scratched	357.90 F	*357.90 F
10	1		*REAR REINFORCEMENT	Serviceable	832.45 F	*- F
11	2		*GASKET	Not Necessary	15.50 F	*- F
12	1		*TAILGATE	Bent	2,241.15 F	*2,241.15 F
13	4		*SLIDER	Necessary	33.80 F	*33.80 F
14	2		*CLIP WITH SE	Necessary	2.80 F	*2.80 F
15	4		*BLIND RIVET	Necessary	12.60 F	*12.60 F
16	3		*ADHESIVE PAD	Necessary	5.40 F	*5.40 F
17	2		*EXPANDING NUT	Necessary	6.10 F	*6.10 F
18	1		*BMW LOGO	Necessary	76.55 F	*76.55 F
19	1		*LABEL X3	Necessary	68.90 F	*68.90 F
20	1		*LABEL SDRIVE20I	Necessary	103.35 F	*103.35 F
21	2		*BUMP STOP	Necessary	10.40 F	*10.40 F
22	1		*REPAIR FLAT	Necessary	154.00 F	*154.00 F
23	4		*VELCRO FASTE	Necessary	12.00 F	*12.00 F
24	1		*REAR LICENCE PLATE WITH CASING	Scratched	70.00 FS	*70.00 FS
25	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)** **7,279.00** **5,907.30**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE / REPLACE REAR BUMPER, TAILGATE AND ALL RELATED DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	2,550.00	1,700.00
2	TO RESPRAY REAR BUMPER AND TAILGATE	New	2,320.00	1,880.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	150.00
4	TO TRANSFER THE TAILGATE MECHANISM	New	850.00	425.00
5	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS	New	560.00	560.00
6	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS	New	180.00	180.00
7	TO TRANSFER THE REVERSE SENSORS	New	500.00	250.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	500.00	500.00
<b>Gross Labour Cost (\$)</b>			<b>7,960.00</b>	<b>5,795.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >