

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI24100458/ANP3E2
Date: 05/11/2024REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMX1072E	Insured Vehicle No :	YP1744A
Date of Loss:	21/10/2024	Nature of Claim:	TP
		Claim No:	CDMCG24002756

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX1072E	Engine No:	3ZZ4867523
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106140743
Reg. Date:	31/03/2009 (Man. Year: 2009)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Gencotire 6 mm	Rear Left Side:	Gencotire 6 mm
Front Right Side:	Gencotire 6 mm	Rear Right Side:	Gencotire 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,347.32	3,900.87	2,446.45	38.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	1,860.00	1,840.00	49.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,047.32	5,760.87	4,286.45	42.66
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	10,047.32	4,600.00	5,447.32	54.22

INSPECTION

Date of Assignment:	24/10/2024	
Date Inspected:	25/10/2024	Inspected At: S L Motor Repair (HQ) 1 Kaki Bukit Avenue 6, #01-95 Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2024)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX1072E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	585.90 FL	*585.90 FL
2	2		*REAR BUMPER SIDE HOLDER	Not Necessary	76.40 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT ROD	Not Necessary	152.60 FL	*- FL
4	1		*REAR BUMPER SPONGE	Cracked	129.20 FL	*129.20 FL
5	2		*REAR BUMPER IMPACT BRACKET	Dented	171.20 FL	*171.20 FL
6	2		*REAR BUMPER REFLECTOR	Not Necessary	138.40 FL	*- FL
7	1		*REAR END PANEL	Dented	686.40 FL	*686.40 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	192.70 FL	*192.70 FL
9	2		*TAILLAMP	Cut	733.80 FL	*733.80 FL
10	2		*TAILLAMP PANEL	Repair	390.80 FL	*- FL
11	2		*TAILLAMP LOWER BRACKET	Not Necessary	110.20 FL	*- FL
12	1		*BOOTLID	Dented	839.40 FL	*839.40 FL
13	1		*BOOTLID LOCK	Damaged	121.50 FL	*121.50 FL
14	1		*BOOTLID WEATHERSTRIPE	Cut	195.50 FL	*195.50 FL
15	2		*BOOTLID HINGE	Not Necessary	145.00 FL	*- FL
16	2		*BOOTLID REFLECTOR	N/S Cracked / O/S Cut	560.60 FL	*560.60 FL
17	1		*BOOTLID INNER TRIM	Not Necessary	172.10 FL	*- FL
18	1		*BOOTLID OUTER CHROME MOULDING	Cracked	274.80 FL	*274.80 FL
19	1		*TOYOTA LOGO	Necessary	52.60 FL	*52.60 FL
20	1		*1.6 EMBLEM	Necessary	46.90 FL	*46.90 FL
21	1		*ALTIS EMBLEM	Necessary	48.50 FL	*48.50 FL
22	1		*COROLLA EMBLEM	Necessary	55.50 FL	*55.50 FL
23	2		*REAR FENDER INNER TRIM	Not Necessary	677.40 FL	*- FL
24	2		*REAR FENDER INNER SHIELD	Not Necessary	97.00 FL	*- FL
25	1		*SPARE TYRE PANEL	Repair	845.90 FL	*- FL
26	1		*SPARE TYRE LOCK SCREW	Not Necessary	42.60 FL	*- FL
27	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	240.20 FL	*- FL
28	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
29	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
30	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
32	1		*TAILLAMP SPONGE GASKET	O/S Necessary	40.00 FS	*20.00 FS
33	1		*SET BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
34	1		*SET BOOTLID OUTER CHROME MOULDING CLIPS	Necessary	10.00 FS	*10.00 FS
35	2		*BOOTLID REFLECTOR SPONGE GASKET	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,293.10	5,074.50
- List Item Discount on L Items 25.00/25.00% (S\$)	1,945.78	1,173.63
Total Parts (S\$)	6,347.32	3,900.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	1,600.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	750.00
3	WIRING CHECK	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
8	TO REMOVE REAR CAMERA	New	100.00	50.00
Gross Labour Cost (S\$)			3,700.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >